

COLUMBIA

CALDWELL PARISH (F86) 2 NE UTC-6(-5DT) N32°07.33' W92°03.27'

MEMPHIS
L-18F

67 B NOTAM FILE DRI

RWY 01-19: H3501X75 (ASPH) S-6 MIRL

RWY 01: REIL. PAPI(P2L)—GA 3.5° TCH 63'. Trees.

RWY 19: REIL. PAPI(P2L)—GA 3.0° TCH 53'.

SERVICE: LGT ACTIVATE MIRL Rwy 01-19—CTAF. REIL Rwy 01-19 opr continuously. Rwy 01 REIL OTS approach end Rwy 01. Rwy 19 REIL OTS approach end Rwy 19.

AIRPORT REMARKS: Unattended. Birds in/ov arpt. Foreign objects and debris present on apron. Grass growing through cracks. Windssock OTS temp.


AIRPORT MANAGER: (318) 331-3888

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Monroe Apch at 318-327-5641, if unavbl, ctc Fort Worth ARTCC at 817-858-7584.

RADIO AIDS TO NAVIGATION: NOTAM FILE MLU.

MONROE (L) VORTACW 117.2 MLU Chan 119 N32°31.01' W92°02.16' 179° 23.7 NM to fld. 76/3E.



CONCORDIA PARISH (See VIDALIA on page 122)

COUSHATTA

THE RED RIVER (ØR7) 2 SE UTC-6(-5DT) N31°59.42' W93°18.46'

HOUSTON
H-6I, L-22E
IAP

177 B NOTAM FILE DRI

RWY 18-36: H5002X74 (ASPH) S-44 MIRL

RWY 18: REIL. PAPI(P2L)—GA 3.0° TCH 50'. Trees.

RWY 36: REIL. PAPI(P2L)—GA 3.0° TCH 50'. Trees.

SERVICE: LGT MIRL Rwy 18-36, REIL Rwy 18 and 36 preset low intst dusk-dawn, to incr intst actvt—CTAF. Rwy 18 and 36 REILS out of service. Rwy 18 and 36 PAPI out of service. Airport beacon out of service.

AIRPORT REMARKS: Unattended. 66' trees 253' east of rwy centerline full length. NOTE: See Special Notices—Aerobatic Practice Area.

AIRPORT MANAGER: 318-932-5710

COMMUNICATIONS: CTAF 122.9

® POLK APP/DEP CON 132.05

CLEARANCE DELIVERY PHONE: For CD ctc Fort Worth ARTCC at 817-858-7584.

RADIO AIDS TO NAVIGATION: NOTAM FILE SHV.

BELCHER (H) VORTACW 117.4 EIC Chan 121 N32°46.28' W93°48.60' 144° 53.3 NM to fld. 190/7E.

