


| | | |
|--|------------------------|--|
| LOC/DME I-AQI 111.75 Chan 54 (Y) | APP CRS 101° | Rwy Idg 10113 TDZE 809 Apt Elev 815 |
|--|------------------------|--|

ILS RWY 10R (SA CAT I & II)
JOHN GLENN COLUMBUS INTL (CMH)

| | | |
|---|-----------|---|
| ADF required. DME or RADAR required. Simultaneous approach authorized. SA CAT I, SA CAT II: Requires specific OPSPEC, MSPEC, or LOA approval. | MALSR | MISSED APPROACH: Climb to 1400 then climbing right turn to 3000 direct BU LOM and hold. |
|---|-----------|---|



| | | | | | |
|------------------------|---|--------------------------------------|-------------------------------|--------------------------|-------|
| D-ATIS 124.6 | COLUMBUS APP CON 125.95 371.975 | COLUMBUS TOWER 132.7 257.8 | GND CON 121.9 348.6 | CLNC DEL 126.3 | CPDLC |
|------------------------|---|--------------------------------------|-------------------------------|--------------------------|-------|



EC-2, 07 SEP 2023 to 05 OCT 2023

EC-2, 07 SEP 2023 to 05 OCT 2023

| | |
|----------|-------------------|
| ELEV 815 | D TDZE 809 |
|----------|-------------------|



| | | | | |
|-----------|-----------|-----------|------------|---|
| CATEGORY | A | B | C | D |
| S-ILS 10R | SA CAT I | RA 146/14 | 150 DA 959 | |
| S-ILS 10R | SA CAT II | RA 99/12 | 100 DA 909 | |

TDZ/CL Rwy 10R-28L
HIRL Rwy 10R-28L and 10L-28R

SA CATEGORY I & II ILS- SPECIAL AIRCREW & AIRCRAFT CERTIFICATION REQUIRED