

## PLYMOUTH

DONALD'S AIR PARK INC (7NC) 8 SE UTC-5(-4DT) N35°43.90' W76°40.28'

CHARLOTTE

18 NOTAM FILE RDU

RWY 04-22: 4195X100 (TURF) LIRL(NSTD)

RWY 04: Brush.

RWY 22: Thld dspclcd 801'. Pole.

SERVICE: S3 LGT To actvt LIRL Rwy 04-22 call 252-809-9010. Rwy 04-22 NSTD LIRL due to spacing of rwy lgts and no end lgts.

AIRPORT REMARKS: Attended Mon-Sat 1300-2200Z, Sun 1800-2200Z. Heavy agricultural acft ops Mar-Nov. Parallel turf rwy arpt within 3/4 mile NW. Rwy 22 has unmkd p-line 60' +/- each side of thld; power poles each side of thld with p-line buried across rwy width at thld. Addnl unmkd 50' p-line 1200' from Rwy 22 thld. Rwy 04 and Rwy 22 mkd with yellow cones. Rwy 4 has 8' ditch 12' from thld both sides cntrln.

AIRPORT MANAGER: 252-809-9010

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Washington ARTCC at 703-771-3587.

COMM/NAV/WEATHER REMARKS: Mnt freq 122.8 for tfc adzy.

PLYMOUTH MUNI (PMZ)(KPMZ) 2 S UTC-5(-4DT) N35°48.65' W76°45.50'

CHARLOTTE

36 B NOTAM FILE RDU

H-9C, 12H, L-35C

RWY 03-21: H5500X75 (ASPH) S-25 MIRL

IAP

RWY 03: REIL. PAPI(P2L)—GA 4.0° TCH 30'. Trees.

RWY 21: REIL. PAPI(P2L)—GA 4.0° TCH 28'. Trees.

SERVICE: FUEL 100LL, JET A1+ LGT Actvt REIL Rwy 03 &amp; 21: PAPI Rwy 03 &amp; 21; MIRL Rwy 03-21—CTAF. Rwy 21 PAPI unusbl byd 8 deg R of cntrln.

AIRPORT REMARKS: Attended 1300-2200Z. Deer activity invof arpt. 24 hr self svc fueling with credit card. For svc after hrs call 252-793-9801. Arpt lctd 5 mi W of mil rstrd area; safety problem due fast mil acft crossing arpt below 3000 ft MSL enroute to rstrd area—crossings are unannounced.

AIRPORT MANAGER: 252-793-9801

COMMUNICATIONS: CTAF/UNICOM 122.8

® CHERRY POINT APP/DEP CON 119.35

CLEARANCE DELIVERY PHONE: For CD ctc Washington ARTCC at 703-771-3587.

RADIO AIDS TO NAVIGATION: NOTAM FILE RDU.

COFIELD (L) (L) VORTACW 114.6 CVI Chan 93 N36°22.37'

W76°52.29' 180° 34.1 NM to fld. 65/9W.

TACAN AZIMUTH unusable:

120°-180° byd 25 NM

180°-120° byd 25 NM blo 3,000'

VOR unusable:

290°-300°

