

MINUTEMAN LAKE SPB (MFN) 1 N UTC-9(-8DT) N61°43.28' W150°02.81'

ANCHORAGE

295 NOTAM FILE ENA

WATERWAY 07W-25W: 1500X50 (WATER)

SEAPLANE REMARKS: Unattended. No svc of any type avbl to tran acft. Seaplane base condition not monitored, recommend visual inspection prior to use. Caution for trees on east end of lake.

AIRPORT MANAGER: 907-355-5310

COMMUNICATIONS: CTAF/UNICOM 122.8

COMM/NAV/WEATHER REMARKS: For a toll free call to Kenai FSS dial 1-866-864-1737.

WILLOW (UUO)(PAUO) 1 NW UTC-9(-8DT) N61°45.25' W150°03.10'

ANCHORAGE

215 B NOTAM FILE ENA

H-1B, 2K, L-1A, 3D, 4F

RWY 13-31: 4400X75 (GRVL) MIRL 0.3% up SE

IAP

RWY 13: Trees.

RWY 31: Thld dspclcd 400'. Trees. Rgt tfc.

SERVICE: S4 FUEL 100LL LGT ACTIVATE MIRL Rwy 13-31—CTAF.

AIRPORT REMARKS: Unattended. Rwy condition not monitored, recommend visual inspection prior to using. Credit card self serve fuel avbl 24 hrs. Rwy 13 NSTD markings, thld marked with flexible reflective markers and cones. Rwy 31 NSTD markings, dspclcd thld marked with reflective flexible markers and cones, twy markings thru dspclcd thld. Float planes on Willow Lake across road.

AIRPORT MANAGER: 907-495-6286

COMMUNICATIONS: CTAF 122.8

Ⓡ ANCHORAGE CENTER APP/DEP CON 133.7

RADIO AIDS TO NAVIGATION: NOTAM FILE ENA.

BIG LAKE (H) (H) VORTACW 112.5 BGQ Chan 72 N61°34.17'

W149°58.03' 329° 11.4 NM to fld. 179/19E.

TACAN AZIMUTH unusable:


230°-245° byd 38 blo 8,000'

DME unusable:

230°-245° byd 38 blo 8,000'

COMM/NAV/WEATHER REMARKS: For a toll free call to Kenai FSS dial

1-866-864-1737. When avbl Wx reports hourly only.



WILLOW SPB (2X2) 1 NW UTC-9(-8DT) N61°44.61' W150°03.58'

ANCHORAGE

200 NOTAM FILE ENA

WATERWAY 13W-31W: 3600X400 (WATER)

SERVICE: S7

SEAPLANE REMARKS: Unattended. Acft run-up area at the NE end of lake is marked by buoys seasonally. No public dock avbl. Grvl public ramp lctd on NE shore of lake. No public parking avbl. Major power plant repairs avbl. No winter maintenance be alert during ldg/tkf. A buoy has been placed aprx 200' from the most southern point of land on the southeast end of the lake. Acft opr are not allowed inside the 200' marker unless taxiing to or from the shore, or taxiing to the acft run-up area. Pilots should be aware of watercraft and recreational activities on the lake. A visual inspection prior to ldg is recommended. Wind indicator avbl at Willow Arpt across the road. Buoys are removed from lake prior to freeze-up and replaced when lake thaws. It is recommended that all acft tkf toward the south, weather conditions permitting. No east/west tkf or ldg are permitted.

AIRPORT MANAGER: 907-495-6286

COMMUNICATIONS: CTAF/UNICOM 122.8

COMM/NAV/WEATHER REMARKS: For a toll free call to Kenai FSS dial 1-866-864-1737.

WINGSONG ESTATES (See DELTA JUNCTION on page 94)