ALASKA

LDEZ	
ROBE LAKE SPB (L93) 6 W UTC-9(-8DT) N61°05.23' W146°03 39 NOTAM FILE JNU WATERWAY E-W: 4000X200 (WATER) WATERWAY N-S: 2000X200 (WATER) SERVICE: FUEL JET A SEAPLANE REMARKS: Unattended. No dock facilities, seaplane beaching area	
Use extreme caution when operating at the seaplane base. Steel bars protruding from the shoreline and water near th shore line. AIRPORT MANAGER: 907-831-1386 COMMUNICATIONS: CTAF 122.9 COMM/NAV/WEATHER REMARKS: For a toll free call to Juneau FSS dial 1–866–297–2236.	
THOMPSON PASS (K55) 17 E UTC-9(-8DT) N61°10.64' W145	41.31 ´ ANCHORA
2080 NOTAM FILE JNU RWY 05-23: 2530X9 (TURF-GRVL)	
RWY 05: Brush.	
RWY 23: Brush.	
AIRPORT REMARKS: Unattended. PPR for ops – amgr. Rwy 05–23 unsafe for	0
Indg, tkof or TGL due to debris on rwy – amgr. Rwy cond unmnt: rcmd	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0
visual insp prior to use. High trrn all quads. Exp turbulent wind. Unctld	
vehicle tfc on rwy. Rwy end 23: Pwr line crosses hill on apch end. Rwy	10000000000000000000000000000000000000
end 05: first 300 ft soft & rutted. 1 ft grass & brush first 1200 ft;	200000000000000000000000000000000000000
remainder 4 ft brush. Rwy 05–23: E side 9 ft usbl; remainder overgrown with 4 ft brush. Rwy 05–23: 4 ft brush E half of rwy; strip 10 ft by 2270	1 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0
ft E side unusbl; sfc soft aft rain; loose gravel & 6 in brush W half of rwy;	1 000 00 mmm
slight rise each end.	1 3 00 Comment
AIRPORT MANAGER: (907) 269-8508	F 63 63
COMMUNICATIONS: CTAF 122.9	Co manufillit
RCO 122.55 (JUNEAU RADIO)	a martine
RADIO AIDS TO NAVIGATION: NOTAM FILE VDZ. Mineral creek NDB (MHW) 524 MNL N61°07.45′	061° 19.6 NM From
MINERAL CREEK NDB (MHW) 524 MNL N61°07.45′ W146°21.13′ 061° 19.6 NM to fld. 21/19E.	Mineral Creek "MNL" NDB
NDB unusable:	
320°-010° byd 15 NM	
COMM/NAV/WEATHER REMARKS: For a toll free call to Juneau FSS dial 1-866-2	97-2236