MARSHALL ISLANDS

ARNO ATOLL

 INE
 (N2Ø)
 0 NW
 UTC+12
 N07°01.00' E171°29.00'

 4
 NOTAM FILE HNL
 Not insp.

 RWY 08-26: 2450X50 (GRVL-CORAL)

 AIRPORT REMARKS: Attended on call.

 COMMUNICATIONS: CTAF 122.9

TINAK (N18) ON UTC+12 N07°08.00´E171°55.00´ 4 NOTAM FILE HNL Not insp. RWY 05-23: 2850X45 (GRVL-CORAL) AIRPORT REMARKS: Attended on call. COMMUNICATIONS: CTAF 122.9

ENEWETAK

ENEWETAK AUX AF (PKMA) (AF) UTC+12 N11°20.45' E162°19.67'

P-1B

13 AOE Not insp.

RWY 06-24: H7700X148 (ASPH) D-106, 2S-134, 2D-170, C5-575

AIRPORT REMARKS: Opr Mon–Sat 2000–0500Z, Enewetak date. Official business only, PPR. Multi unlighted twr up to 100^{-/} in vicinity rwy. Rwy badly deteriorated, emergency Idg only. IFR acft arr Enewetak remain in ctc with Hickam till cleared to Enewetak Radio. Request 2 hour eta notice. No com watch on radio freq outside normal hour of opr. Arr acft trans in blind on 121.5 acft call sign, ETA–100 NM from station. 2 trans, 3 min intervals, IFR dep clnc fr Hickam. COMM/NA/WEATHER REMARKS: TrmI advisory svc.

JABOR JALUIT ATOLL

JALUIT (N55) 1 SE UTC+12 N05°54.40′ E169°38.50′ 4 NOTAM FILEHNL Not insp. RWY03-21: 5000X60 (GRVL-CORAL) SERVICE: FUEL 100 AIRPORT REMARKS: Attended on call. Fuel used for local operations only. For refueling contact Air Marshall Islands (692) 93731. COMMUNICATIONS: CTAF 122.9

KILI ISLAND

 KILI
 (C51)
 0 N
 UTC+12
 N05°39.00'
 E169°07.00'
 5
 NOTAM FILE HNL
 Not insp.
 RWY 04-22:
 4400X100 (GRVL-CORAL)
 AIRPORT REMARKS: Attended on call.
 COMMUNICATIONS: CTMF 122.9
 Communication
 Communication
 Communication
 Call of the call of th