

25163

ILS RWY 19L (CAT II)
TAMPA INTL (TPA)

MISSED APPROACH: Climb to 600 then climbing left turn to 4000 on heading 160° and on PIE VORTAC R-138 to GIBBS INT and hold.

[illegible]

REIL Rwy 1R
 TDZ/CL Rwsys 1L and 19L
 HIRL Rwsys 1L-19R, 1R-19L, and 10-28

600 ↑	4000 hdg 160°	PIE R-138	GIBBS INT	VGSi and ILS glidepath not coincident (VGSi Angle 3.00°/TCH 74).			
				POMSE INT I-TPA <u>7.6</u> 2000 187° 3000 BUCCS I-TPA <u>10.7</u> RADAR GS 3.00° TCH 51			
CATEGORY S-ILS 19L	A	B	C	D	RA 100/12 100 DA 126		

CATEGORY II ILS - SPECIAL AIRCREW
& AIRCRAFT CERTIFICATION REQUIRED

TAMPA INTL (TPA)

ILS RWY 19L (CAT II)

SE-3, 12 JUN 2025 to 10 JUL 2025