LOC/DME I-DDO	APP CRS	Rwy Idg	10000
110.5	005°	TDZE	88
Chan 42		Apt Elev	96

ILS RWY 35L (CAT II & III)

ORLANDO INTL (MCO)

DME or RADAR required. Bright lights on highway midway between Rwy 35L and Rwy 35R may be mistaken for runway lights. Simultaneous approach authorized. When using alternate missed approach, simultaneous approach NA.

ALSF-2

MISSED APPROACH: Climb to 3000 on heading 005° and ORL VORTAC R-049 to OVIDO INT/ORL 13 DME and hold.

D-ATIS	ORLANDO APP CON	ORLANDO TOWER	GND CON	CLNC DEL	
ARR 121.25	124.8 307.0	124.3 (Rwys 18L-36R,18R-36L) 253.5	126.4 275.8 (East)	134.7	CPDLC
DEP 120.525		118.45 (Rwys 17L-35R,17R-35L) 253.5	121.8 275.8 (West)	341.7	

RADAR REQUIRED

MLB R-329

ORLANDO 112.2 ORL Chan 59

LOCALIZER 110.5 I-DDO Chan 42

OVIDO ORL 13

049° 229°

R-049

1749±

1749

110.0 MLB Chan 37

Executive

ALTERNATE MISSED APCH FIX

113.7 OCF Chan 84

112.6 OMN Chan 73

193° 013°

R-114

R-193

ZOKUM OMN 31.8

215

353

464

214

346

IM 166±

549

1949

MSA ORL 25 NM

3000

SPURR I-DDO 6.4 RADAR

1600 005° (4.4)

FITEM I-DDO 10.8 RADAR

(IF) FOBUK I-DDO 14 RADAR

3000 005° (3.2)

(IAF) NOGGI I-DDO 16.5 RADAR

4000 005° (2.5) 185°

ELEV 96 D TDZE 88

18R 18L 17L 17R 12004 X 200 12005 X 200 10000 X 150 10006 X 150 TWR 437± 194 36L 36R 35R 35L

HIRL all Rwys
REIL Rwy 36L
TDZ/CL Rwys 17L/R, 18R, 35L/R and 36R

3000	hdg 005°	ORL R-049	OVIDO

VGSI and ILS glidepath not coincident (VGSI Angle 3.00/TCH 72).



CATEGORY	A	B	C	D
S-ILS 35L	CAT II RA 106/12 100 DA 188			
S-ILS 35L	CAT III RVR 06			

CATEGORY II & III ILS - SPECIAL AIRCREW & AIRCRAFT CERTIFICATION REQUIRED

SE-3, 10 OCT 2019 to 07 NOV 2019
SE-3, 10 OCT 2019 to 07 NOV 2019