SUGARLOAF RGNL (See CARRABASSETT on page 62)

SWANS FLD (See DIXFIELD on page 64)

SWANS ISLAND

BANKS (ME5) 5 N UTC–5(–4DT) N44º09.92´ W68º25.69´ **HALIFAX**
100 NOTAM FILE BGR
RWY 10–28: 1500X30 (GRVL) 2.0% up W
RWY 10: Tree.
RWY 28: Thld dsplcd 300´. Bldg.
RUNWAY DECLARED DISTANCE INFORMATION
RWY 10: TORA–1500 TODA–1500 ASDA–1500 LDA–1500
RWY 28: TORA–1500 TODA–1500 ASDA–1500 LDA–1200
AIRPORT REMARKS: Unattended. Prior to using arpt call 207–460–1113. All ops rstd to dalgt VFR only. Wildlife on or invof arpt. Rwy 10–28 +6´ rock ledge 50´ from centerline south side of arpt. Rwy 10 has +15´ trees 50´ rgt of centerline 430´ from thld. Rwy 10–28 sfc rough with large stones, steep gradients and no line of sight between ends. Rock drainage swale across 600´ from Rwy 28, approximately 40´ wide at centerline.
AIRPORT MANAGER: 207-596-7500
COMMUNICATIONS: CTAF 122.9
CLEARANCE DELIVERY PHONE: For CD ctc Bangor Apch at 207-561-2521.

• • • • • • • • • • • • • • • • • •

HELIPAD H1: H40X40 (CONC)
HELIPORT REMARKS: Helipad coords 44 09 54.80N 68 25 48.80W; helipad elev 86´. Ingress and egress to helipad between 130º and 320º mag.

TURNER

TWITCHELL (3B5) 4 S UTC–5(–4DT) N44º11.34´ W70º13.97´ **NEW YORK**
355 NOTAM FILE BGR
RWY 11–29: 2151X100 (TURF)
RWY 11: Road.
RWY 29: Trees.
RWY 12–30: H2104X50 (ASPH) S–8.5 0.3% up W
RWY 12: Trees.
RWY 30: Trees.
SERVICE: S4 **FUEL** 100LL, MOGAS
AIRPORT REMARKS: Attended 1300–2200Z‡. For fuel, maintenance or seaplane information call 207–225–3490 or 207–312–4165 for FBO. Emerg phone 207–312–4165. Turkeys, geese on or invof arpt. Rwy 12, first 300´ of rwy unmarked. Rwy 11, +38´ P–line 140–180´ from thld marked with balls across apch. Rwy 29, +20´ pole 145´ from end of rwy, 30´ right of centerline; +25´ bldg 145´ from end of rwy, 90´ right of centerline. Rwy 12–30 numbers and centerline NSTD length and width.
AIRPORT MANAGER: 207-225-3490
COMMUNICATIONS: CTAF/UNICOM 122.8
APP/DEP CON 125.5
CLEARANCE DELIVERY PHONE: For CD ctc Portland Apch at 207-874-7320, when Apch clsd ctc Boston ARTCC at 603-879-6859.

• • • • • • • • • • • • • • • • • •

WATERWAY 04W–22W: 10000X1000 (WATER)
WATERWAY 15W–33W: 5000X1000 (WATER)

TWITCHELL (See TURNER on page 82)

VAN BUREN SPB (Ø5B) 0 N UTC–5(–4DT) N47º09.54´ W67º55.92´ **HALIFAX**
440 LRA NOTAM FILE BGR
WATERWAY NW–SE: 4000X200 (WATER)
WATERWAY SE: Bridge.
SEAPLANE REMARKS: Unattended. Clsd Oct 15–May 15 yearly. Access difficult due to construction of new border patrol facility. Dock located near base of bridge. Flight Notification Service (ADCUS) available. U.S. Customs avbl 24 hrs, 207–868–3391.
AIRPORT MANAGER: 207-868-2886
COMMUNICATIONS: CTAF 122.9
CLEARANCE DELIVERY PHONE: For CD ctc Boston ARTCC at 603-879-6859.