OCEAN ISLE BEACH

ODELL WILLIAMSON MUNI (6ØJ) 1 N UTC–5(–4DT) N33º54.56´ W78º26.08´ **CHARLOTTE**
33 NOTAM FILE RDU **L–35A**
RWY 06–24: H4198X75 (ASPH) S–12 MIRL
RWY 06: PAPI(P2L)—GA 3.67º TCH 45´. Tree.
RWY 24: PAPI(P2L)—GA 3.0º TCH 39´. Thld dsplcd 189´. Trees.
SERVICE: FUEL 100LL **LGT** Actvt MIRL Rwy 06–24—CTAF. PAPI Rwy 06 & Rwy 24 operate consly.
AIRPORT REMARKS: Attended Jun–Aug Tue–Sun 1500–2200Z‡, Sep–May Sat–Sun 1500–2100Z‡. Mon–Fri on call 910–575–7575; for service after hours call 845–629–0626. 24 hr self svc fuel with credit card. Sight–seeing tour opns invof arpt. Rwy 06 has 48 ft marked transistional power line +/– 1000 ft from thr. Caution–DTFC shud vfy no ltfc before blocking only rwy exit. Parallel twy byd ramp is clsd. 24 hr pilot lounge – emerg freq allows aces.
AIRPORT MANAGER: 910-599-5651
COMMUNICATIONS: CTAF 122.9
CLEARANCE DELIVERY PHONE: For CD ctc Myrtle Beach Apch at 843-477-2727 or 843-477-2704. When Apch clsd ctc Jacksonville ARTCC at 904-845-1592.
RADIO AIDS TO NAVIGATION: NOTAM FILE CRE.
GRAND STRAND (VL) (H) VORTACW 114.4 CRE Chan 91 N33º48.83´ W78º43.47´ 071º 15.6 NM to fld. 27/3W.
TACAN AZIMUTH unusable:
296º–335º
DME unusable:
296º–335º
VOR unusable:
000º–005º byd 40 NM
016º–020º byd 40 NM
040º–053º byd 40 NM blo 2,500´
040º–053º byd 47 NM
060º–085º byd 40 NM
130º–140º byd 40 NM
205º–222º byd 40 NM blo 7,000´
205º–222º byd 82 NM
292º–296º byd 40 NM
296º–308º byd 30NM blo 5,000´
330º–334º byd 40 NM

OCRACOKE ISLAND (W95) 1 E UTC–5(–4DT) N35º06.07´ W75º57.96´ **CHARLOTTE**
4 B NOTAM FILE RDU **L–35C**
RWY 06–24: H2998X60 (ASPH) S–30 **IAP**
RWY 06: Brush.
RWY 24: Trees.
AIRPORT REMARKS: Unattended. Arpt CLOSED 30 min after SS until 30 min before SR. Rwy not lgtd–night ops prohibited. Flocks of seagulls on and near rwy around standing water after heavy rains. Rwy subject to residual flooding during and after heavy rain. High speed low level mil ops invof arpt. Rwy safety area is loose sand; not suitable for acft. Arpt is within Cape Hatteras National Seashore. Maintain 2000´ vertical and horizontal distance from seashore beaches. Key code access to pilot lounge.
AIRPORT MANAGER: 252-475-9000
COMMUNICATIONS: CTAF 122.9
Ⓡ**CHERRY POINT APP/DEP CON** 119.75NORTH
CLEARANCE DELIVERY PHONE: For CD ctc Washington ARTCC at 703-771-3587.
RADIO AIDS TO NAVIGATION: NOTAM FILE EWN.
NEW BERN (L) (L) VOR/DME 113.6 EWN Chan 83 N35º04.39´ W77º02.70´ 096º 53.2 NM to fld. 16/8W.
VOR unusable:
105º–160º
168º–187º byd 30 NM
221º–260º byd 30 NM blo 6,000´
261º–271º byd 30NM blo 3,000´
272º–290º byd 30 NM
293º–306º byd 30 NM
333º–351º byd 30 NM
DME unusable:
109º–118º byd 30 NM
291º–320º byd 30 NM
355º–005º byd 30 NM

• • • • • • • • • • • • • • • • • • •

HELIPAD H1: H100X100 (CONC) PERIMETER LGTS
HELIPAD H1: Trees.
HELIPORT REMARKS: Helipad for emerg ops only. H1 best apch from NE or SW. Actvt Helipad perimeter lgts only—CTAF. Actvt heli beacon–CTAF. Windsock for helipad lgtd. 30´ power line along NC Hwy 12 NW of helipad.