COLLEGE PLACE

MARTIN FLD (S95) 1 W UTC–8(–7DT) N46º02.82´ W118º25.03´ **SEATTLE**
750 NOTAM FILE SEA **L–13A**
RWY 05–23: H3819X60 (ASPH) S–12 LIRL(NSTD)
RWY 05: VASI(V2L).
RWY 23: VASI(V2R). Road.
SERVICE: S2 **FUEL** 100LL **LGT** Rwy 05–23 NSTD LIRL southwest 1240´ medium ints. Arpt lgtg opr from dusk until 1000Z‡. ACTIVATE NSTD LIRL Rwy 05–23 and VASI Rwy 05 and Rwy 23—CTAF.
AIRPORT REMARKS: Attended Mon–Fri 1600–0100Z‡. Call in advn 509–386–0000. 24 hr self svc credit card fueling facility. Gliders and other acft perform ops on turf btn Rwy 05–23 and twy. Overnight parking fee of $3.00. Pvt road crosses 700´ from southwest end of rwy. 2/3 of the rwy has wdspr, opn, unsealed cracks and joints, hi lvl of raveling and alligator cracking. Ldg fee.
AIRPORT MANAGER: 509-386-0000
COMMUNICATIONS: CTAF/UNICOM 122.8
CLEARANCE DELIVERY PHONE: For CD ctc Spokane Apch at 509-742-2525, when Apch clsd ctc Seattle ARTCC at 253-351-3694.
RADIO AIDS TO NAVIGATION: NOTAM FILE ALW.
WALLA WALLA (VL) (DH) VORW/DME 116.4 ALW Chan 111 N46º05.22´ W118º17.55´ 231º 5.7 NM to fld. 1150/14E.
VOR unusable:
016º–071º byd 31 NM blo 12,500´
032º–042º byd 40 NM blo 12,500´
032º–042º byd 62 NM
042º–169º byd 40 NM
071º–101º byd 20 NM blo 14,500´
101º–146º byd 20 NM blo 13,500´
256º–285º byd 40 NM
286º–296º byd 40 NM blo 4,000´
286º–296º byd 50 NM
291º–302º byd 40 NM
309º–319º byd 40 NM blo 4,000´
309º–319º byd 85 NM
320º–031º byd 40 NM
DME unusable:
071º–101º byd 20 NM blo 14,500´
116º–071º byd 31 NM blo 12,500´
146º–151º byd 20 NM blo 11,500´

COLVILLE MUNI (63S) 1 E UTC–8(–7DT) N48º32.65´ W117º53.01´ **SEATTLE**
1888 B NOTAM FILE SEA
RWY 01–19: H2695X40 (ASPH) S–11 MIRL
RWY 19: Tree.
SERVICE: **FUEL** 100LL **LGT** Dusk–dawn. ACTIVATE MIRL Rwy 01–19—CTAF.
AIRPORT REMARKS: Attended Mon–Fri 1600–0100Z‡. Watch for deer on and invof arpt. Rwy 19 dthr 255´. When ldg Rwy 19, bright lgts around high school stadium, aprx 3/4 miles south of arpt. Ocnl vehicular tfc across end of Rwy 01–19 and twy. Grass ldg area avbl across Rwy 01–19 1500´X150´. Hazards are 50´ obst on both ends, trees/poles. Apron and tiedown grvl; 3 asph paved transient tiedowns westside. Eastside tiedowns gravel. 2 car avbl.
AIRPORT MANAGER: 509-685-9056
WEATHER DATA SOURCES: AWOS–3 119.275 (509) 684–8994.
COMMUNICATIONS: CTAF/UNICOM 122.8
CLEARANCE DELIVERY PHONE: For CD ctc Seattle ARTCC at 253-351-3694.

CONCRETE

MEARS FLD (3W5) 1 S UTC–8(–7DT) N48º31.79´ W121º45.49´ **SEATTLE**
267 NOTAM FILE SEA
RWY 07–25: H2609X60 (ASPH) S–12
RWY 07: Trees. Rgt tfc.
RWY 25: Trees.
SERVICE: **FUEL** 100LL
AIRPORT REMARKS: Unattended. Elk and deer freq both rwy ends and mid–fld. All patterns south of arpt.
AIRPORT MANAGER: 425-322-8582
COMMUNICATIONS: CTAF 122.9
CLEARANCE DELIVERY PHONE: For CD ctc Seattle ARTCC at 253-351-3694.

• • • • • • • • • • • • • • • • • •

HELIPAD H1: H40X40 (CONC)
HELIPORT REMARKS: Helipad for emerg use only.