ERROL (ERR)(KERR) 1 NW UTC–5(–4DT) N44°47.53´ W71°09.87´ **MONTREAL**
1248 TPA—2048(800) NOTAM FILE BGR
RWY 15–33: 3600X60 (GRVL) 0.3% up SE
RWY 15: Trees.
AIRPORT REMARKS: Unattended. For arpt information and conditions, call 603–482–3320. Wildlife on and invof arpt. Regular construction vehicle tfc on roadway at Rwy 33 end. 1:1 clearance slope. Rwy 15–33: Rwy soft in spring. Lrg patches of grass on rwy.
AIRPORT MANAGER: 603-616-8602
COMMUNICATIONS: CTAF/UNICOM 122.8
CLEARANCE DELIVERY PHONE: For CD ctc Boston ARTCC at 603-879-6859.

• • • • • • • • • • • • • • • • • •

HELIPAD H1: H61X61 (ASPH)
HELIPAD H1: Trees.
HELIPORT REMARKS: ACTIVATE helipad flood lgt and lighted windcone—CTAF.

FITZY N42°51.85´ W71°31.73´ NOTAM FILE MHT. **NEW YORK**
NDB (LOMW) 209 MJ 060° 5.8 NM to Manchester Boston Rgnl. 234/15W.

FRANCONIA (1B5) 2 S UTC–5(–4DT) N44°11.76´ W71°45.04´ **MONTREAL**
975 NOTAM FILE BGR
RWY 18–36: 2300X150 (TURF) 0.9% up S
RWY 18: Trees.
RWY 36: Pole. Rgt tfc.
NOISE: Tkofs and ldgs not adzd fm dusk to 1400Z‡ for voluntary noise abatement.
AIRPORT REMARKS: Attended May–Oct Sat–Sun 1500–2300Z‡. Also atndd on wkday hols. Ctc amgr for non–hol wkday atndnc. Wildlife on and invof arpt. Glider opr invof arpt. For arpt conditions call 603–823–5034. Rwy soft in spring. First 200 ft of Rwy 18 rough. Avoid flying over residential area at departure end Rwy 18 during both takeoff and landing, avoid low alt and/or high power settings in this area. 4´ tall fence 92´ fm Rwy 36 L to R of cntrln. Rwy 36 Rgt tfc: L pat for gldrs. In case of emergency ctc New Hampshire State Police 800–525–5555.
AIRPORT MANAGER: 603-921-1588
COMMUNICATIONS: CTAF/UNICOM 122.8
CLEARANCE DELIVERY PHONE: For CD ctc Boston ARTCC at 603-879-6859.

GIFFORD FLD (See COLEBROOK on page 144)

GORHAM (2G8) 1 NW UTC–5(–4DT) N44°23.61´ W71°11.89´ **MONTREAL**
835 NOTAM FILE BGR
RWY 12–30: 2828X60 (TURF) 1.2% up SE
RWY 12: Thld dsplcd 250´. Trees.
RWY 30: Thld dsplcd 250´. Trees.
AIRPORT REMARKS: Unattended. Arpt CLOSED Nov 1–May 15. Otr times ck NOTAMS or durg nml bus hrs only call 603–466–3302, lve fone nr and exp rtrn call for FICON. Wildlife on and invof arpt. Rflg and maint of acft is prohibited. Arpt oprd and maint by Town of Gorham Water and Sewer Dept. AER 30 soft in spring/heavy rains. Rwy sfc rolling and uneven. Rwy 12–30 edges and ends mkd by yellow cones. Camping prohibited on arpt.
AIRPORT MANAGER: 603-466-5065
COMMUNICATIONS: CTAF/UNICOM 122.8
CLEARANCE DELIVERY PHONE: For CD ctc Boston ARTCC at 603-879-6859.

HAMPTON AIRFIELD (7B3) 2 N UTC–5(–4DT) N42°57.68´ W70°49.81´ **NEW YORK**
93 NOTAM FILE BGR
RWY 02–20: H2105X121 (ASPH–TURF) LIRL(NSTD) 0.3% up N
RWY 02: Trees.
RWY 20: Thld dsplcd 212´. Trees.
SERVICE: S3 **FUEL** 100LL, MOGAS **LGT** Rwy 02–20 NSTD LIRL. CTC AMGR at 603–817–6617 for activation instructions.
AIRPORT REMARKS: Attended 1300–2100Z‡, exc Thanksgiving and Christmas. Wildlife on and invof arpt. Self–svc 100LL and MOGAS avbl 24 hrs via credit card. Caution: short and soft fld ops. For short fld trng or info pls ctc amgr 603–817–6617. Extensive student pilot and training ops at arpt. Parallel rwy ops not permitted. Pilot will designate and make radio call to adz turf or grass ldg/tkof. Numerous NORDO acft opr at arpt. Road at Rwy 20 thld with moderate vehicle tfc. Rwy 02–20 2105 ft X 46 ft asph on W portion, 2105 ft X 75 ft on E portion. Rwy 20 NSTD dthr; sngl red/green lgt each side. Thr siting sfc 10:1 slp.
AIRPORT MANAGER: 603-964-6749
COMMUNICATIONS: CTAF/UNICOM 122.8
CLEARANCE DELIVERY PHONE: For CD ctc Boston Apch at 603-594-5552.