JOHNSON

STANTON CO MUNI (JHN)(KJHN) 2 NE UTC–6(–5DT) N37°35.12′ W101°43.94′ **WICHITA**
3325 B NOTAM FILE ICT **L–10G, 15B**
RWY 17–35: H5200X75 (CONC) S–34, D–46 PCN 11 R/C/X/U MIRL **IAP**
RWY 17: PAPI(P4L)—GA 3.0° TCH 40′.
RWY 35: PAPI(P4L)—GA 3.0° TCH 40′.
RWY 08–26: H1889X60 (ASPH) S–3 PCN 4 R/C/Y/U
SERVICE: S4 **FUEL** 100LL, JET A **OX** 1 **LGT** ACTVT MIRL 17–35; to incr intst and ACTVT PAPI Rwy 17 and 35—CTAF.
AIRPORT REMARKS: Attended 1400–0000Z‡. PAEW adjacent all rwys. Rwy 08–26 surface cracking. Twy adjacent to Rwy 17–35 parallel twy unmarked.
AIRPORT MANAGER: 580-330-0589
WEATHER DATA SOURCES: AWOS–3PT 124.175 (620) 492–2100.
COMMUNICATIONS: CTAF/UNICOM 122.8
Ⓡ **KANSAS CITY CENTER APP/DEP CON** 125.2
CLEARANCE DELIVERY PHONE: For CD ctc Kansas City ARTCC at 913-254-8508.
RADIO AIDS TO NAVIGATION: NOTAM FILE LBL.
LIBERAL (H) TACAN Chan 70 LBL (112.3) N37°02.66′ W100°58.27′ 301° 48.8 NM to fld. 2881/11E.
TACAN AZIMUTH unusable:
240°–280°



JOHNSON CO EXEC (See OLATHE on page 128)

JUNCTION CITY

FREEMAN FLD (3JC) 1 NW UTC–6(–5DT) N39°02.60′ W96°50.60′ **KANSAS CITY**
1102 B NOTAM FILE ICT **L–10I**
RWY 18–36: H3498X75 (ASPH) S–10 PCN 5 F/C/Y/U MIRL(NSTD) **IAP**
0.4% up S
RWY 18: PAPI(P2L)—GA 3.0° TCH 43′. Pole.
RWY 36: PAPI(P2L)—GA 3.5° TCH 43′. Pole.
RWY 13–31: 1903X140 (TURF)
RWY 13: Trees.
RWY 31: Trees.
RWY 05–23: 1834X200 (TURF) 0.5% up S
RWY 05: Trees.
RWY 23: Pole.
SERVICE: S4 **FUEL** 100LL, JET A **LGT** ACTVT PAPI Rwy 36; MIRL Rwy 18/36—CTAF. Rwy 18 & 36 nstd thld lgts: color and six lgt delineation. Rwy 18 REIL lgt knocked ovr offset R.
AIRPORT REMARKS: Attended 1400–2300Z‡. Waterfowl on and invof arpt. NSTD air traffic control minima applied IFR arrivals with respect to high performance acft ops conducted within confines of R–3602. Apch end of Rwy 13 is delineated with blue and white plastic barrels. Apch end Rwy 31 is delineated with blue and white barrels and yellow painted tires. Rwy, twy and apron cond fair, turf soft when wet. Baseball field lgt poles 918 ft to 1303 ft from rwy end, 338 ft to 672 ft right, 1175 AMSL. Cold temperature airport. Altitude correction required at or below –23C.
AIRPORT MANAGER: (785) 761-7692
COMMUNICATIONS: CTAF/UNICOM 122.8
Ⓡ **MARSHALL AAF GCA APP/DEP CON** 121.25 (Mon–Thu 1400–0700Z‡; Fri 1400–2200Z‡, exc hol other times ctc)
Ⓡ **KANSAS CITY CENTER APP/DEP CON** 127.35 (Mon–Fri 0700–1400Z‡; Fri 2200–1400Z‡, exc hol)
CLEARANCE DELIVERY PHONE: For CD ctc Marshall Apch at 785-239-2118. When Marshall Apch is clsd, ctc Kansas City ARTCC at 913-254-8508.
RADIO AIDS TO NAVIGATION: NOTAM FILE SLN.
SALINA (VH) (H) VORTACW 117.1 SLN Chan 118 N38°55.51′ W97°37.28′ 072° 37.1 NM to fld. 1316/7E.
VOR unusable:
017°–026° byd 40 NM
315°–016° byd 15 NM blo 6,000′
DME unusable:
300°–042° byd 15 NM blo 6,000′
COMM/NAV/WEATHER REMARKS: FBO phone: 785–761–7692.



KEARNY CO (See LAKIN on page 113)