SCHUYLERVILLE

GARNSEYS (BØ4) 1 S UTC–5(–4DT) N43º04.06´ W73º35.03´ **NEW YORK**

100 NOTAM FILE BTV

RWY 02–20: 2500X90 (TURF)

RWY 02: Road.

RWY 20: Road.

AIRPORT REMARKS: Attended May–Sep dalgt hours. Arpt open dalgt hours only. Numerous buildings in apch to Rwy 20. Tiedowns located immediately north of driveway adjacent to Rwy 20 end.

AIRPORT MANAGER: 518-469-9472

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Albany Apch at 518-862-2299.

• • • • • • • • • • • • • • • • • •

WATERWAY 02W–20W: 9999X750 (WATER)

SENECA FALLS

FINGER LAKES RGNL (ØG7) 2 SE UTC–5(–4DT) N42º53.01´ W76º46.87´ **NEW YORK**

492 B NOTAM FILE BUF **L–32F**

RWY 01–19: H4592X75 (ASPH) S–12.5, D–30 MIRL **IAP**

RWY 01: REIL. PAPI(P2L)—GA 3.0º TCH 40´. Thld dsplcd 392´. Trees.

RWY 19: REIL. PAPI(P2L)—GA 3.0º TCH 40´. Crops.

RWY 11–29: 1850X60 (TURF) 1.3% up W

RWY 11: Trees.

RWY 29: Trees.

RUNWAY DECLARED DISTANCE INFORMATION

RWY 01: TORA–4592 TODA–4592 ASDA–4592 LDA–4199

RWY 19: TORA–4592 TODA–4592 ASDA–4592 LDA–4292

SERVICE: S4 **FUEL** 100LL, JET A **LGT** ACTIVATE REIL Rwy 01 and Rwy 19; MIRL Rwy 01–19—CTAF.

AIRPORT REMARKS: Attended 1300–2100Z‡. Medivac heliport flight svc on arpt, monitor CTAF for ops. Ldg fee. Ldg fee for jets and turbo props.

AIRPORT MANAGER: 315-539-1640

WEATHER DATA SOURCES: AWOS–3 120.0 (315) 568–5362.

COMMUNICATIONS: CTAF/UNICOM 122.8

Ⓡ **ELMIRA APP CON** 124.3 (SW–SE) (1100–0500Z‡)

Ⓡ **NEW YORK CENTER APP CON** 133.35 (SW–SE) (0500–1100Z‡)

Ⓡ **ROCHESTER APP CON** 119.55 (W–NW)

Ⓡ **SYRACUSE APP/DEP CON** 126.125

CLEARANCE DELIVERY PHONE: For CD ctc Syracuse Apch at 315-455-6218.

RADIO AIDS TO NAVIGATION: NOTAM FILE ITH.

ITHACA (L) DME 111.8 ITH Chan 55 N42º29.70´ W76º27.58´ 329º 27.3 NM to fld. 1112.

DME unusable:

360º–160º byd 20 NM blo 6,500´

SHARON (K31) 2 SE UTC–5(–4DT) N42º46.70´ W74º34.66´ **NEW YORK**

1508 NOTAM FILE BUF

RWY 13–31: 2570X120 (TURF)

RWY 13: Thld dsplcd 200´. Trees.

RWY 31: Trees.

AIRPORT REMARKS: Attended irregularly. P–line parallel on SW side of rwy 285 ft from rwy edge. Rwy shortened by 200´ on the west end due to turf holes/crevasses. Trees encroaching NE side of rwy.

AIRPORT MANAGER: 518-284-2081

COMMUNICATIONS: CTAF/UNICOM 122.8

CLEARANCE DELIVERY PHONE: For CD ctc Syracuse Apch at 315-455-6218.