

**DICKINSON/THEODORE ROOSEVELT RGNL** (DIK)(KDIK) 5 S UTC-7(-6DT) N46°48.03' W102°48.27'

**BILLINGS**  
H-2H, L-14F  
IAP, AD

2592 B TPA—See Remarks Class I, ARFF Index A NOTAM FILE DIK

**RWY 14-32:** H7301X150 (CONC-GRVD) S-60, D-90, 2D-90

PCN 25 R/B/W/T HIRL

**RWY 14:** REIL. PAPI(P4L)—GA 3.0° TCH 50'. Pole.

**RWY 32:** MALSR. PAPI(P4L)—GA 3.0° TCH 50'. Road.

**RWY 07-25:** H4700X75 (ASPH-GRVD) S-16, D-20 PCN 5 F/D/W/T

MIRL 0.4% up E

**RWY 07:** REIL. PAPI(P2L)—GA 3.0° TCH 28'.

**RWY 25:** REIL. PAPI(P2L)—GA 3.0° TCH 28'. Road.

**RUNWAY DECLARED DISTANCE INFORMATION**

**RWY 07:** TORA-4700 TODA-4700 ASDA-4700 LDA-4700

**RWY 14:** TORA-7301 TODA-7301 ASDA-7301 LDA-7301

**RWY 25:** TORA-4700 TODA-4700 ASDA-4700 LDA-4700

**RWY 32:** TORA-7301 TODA-7301 ASDA-7301 LDA-7301

**SERVICE:** S4 FUEL 100LL, JET A LGT ACTVT MALSR Rwy 32; REIL

Rwy 14, 07 and 25; PAPI Rwy 07, 25, 14 and 32; HIRL Rwy 14-32—CTAF. MIRL Rwy 07-25 preset on low instst dusk-0500Z‡; to incr instst aft 0500Z‡—CTAF.

**AIRPORT REMARKS:** Attended 1400-2300Z‡. Haying operations adjacent

to all surfaces Jun-Sep. Airfield sfc conds unmon btn 0600 and

1130Z‡. For svc after hrs call 701-264-9966. Rwy 07-25 not avbl for skedd acr opns with more than 9 psgr seats or

unsked acr at least 31 psgr seats. Crop dusting operations invof arpt. PAEW on movement areas during winter (Oct-Apr).

TPA—single engine 3602 (1010); multiengine 4102 (1510). Conc apron for heavy acft parking.

**AIRPORT MANAGER:** 701-483-1062

**WEATHER DATA SOURCES:** ASOS 118.375 (701) 227-0280.

**COMMUNICATIONS:** CTAF/UNICOM 123.0

RCO 122.2 (GRAND FORKS RADIO)

Ⓜ **MINNEAPOLIS CENTER APP/DEP CON** 124.25

**CLEARANCE DELIVERY PHONE:** For CD if una to ctc on FSS freq, ctc Minneapolis ARTCC at 651-463-5588.

**AIRSPACE:** CLASS E.

**RADIO AIDS TO NAVIGATION:** NOTAM FILE DIK.

(VH) (H) VORTACW 112.9 DIK Chan 76 N46°51.60' W102°46.41' 186° 3.8 NM to fld. 2527/14E.


VOR unusable:

010°-020° byd 40 NM blo 18,000'

180°-230° byd 40 NM

260°-270°

ILS/DME 108.3 I-DIK Chan 20 Rwy 32. Class IE. Unmonitored.



**DRAYTON MUNI** (D29) 3 N UTC-6(-5DT) N48°37.11' W97°10.55'

**TWIN CITIES**

798 B NOTAM FILE GFK

**RWY 17-35:** H2596X60 (ASPH) S-4 LIRL

**RWY 35:** Thld dsplcd 505'.

**SERVICE:** LGT LIRL Rwy 17-35 opr dusk-0600Z‡, after 0600Z‡, ACTIVATE LIRL Rwy 17-35—CTAF.

**AIRPORT REMARKS:** Unattended. For svc call 701-454-6588. Confirm winter conditions and snow removal before use, call 701-454-3590 or 701-454-6588. Rwy 35 dsplcd thld ngt ops only. Rwy 17 cultivated fld 20 ft fm thr. Rwy 17 mks heavily worn & faded. Rwy 35 mks heavily worn & faded.

**AIRPORT MANAGER:** 701-520-1219

**COMMUNICATIONS:** CTAF 122.9

**CLEARANCE DELIVERY PHONE:** For CD ctc Minneapolis ARTCC at 651-463-5588.

**DUNN CO WEYDAHL FLD** (See KILLDEER on page 352)