

**HARBOR SPRINGS** (MGN)(KMGN) 3 E UTC-5(-4DT) N45°25.53' W84°54.81'

LAKE HURON

686 B NOTAM FILE MGN

L-31B

**RWY 10-28:** H4149X75 (ASPH) S-22, D-30 MIRL


IAP

**RWY 10:** PAPI(P4R)—GA 3.5° TCH 28'. Thld dsplcd 437'. Tree.**RWY 28:** PAPI(P4L)—GA 4.0° TCH 35'. Thld dsplcd 444'. Pole.**SERVICE:** FUEL 100LL, JET A+ LGT Actvt MIRL Rwy 10-28—CTAF. PAPI Rwy 10 and 28 opr constly. Rwy 28 PAPI unusable byd 2° left of centerline.**NOISE:** Noise abatement procedures; no turbojet/turbofan acft depts frm 0400-1200Z±, no low flight ovr surrounding community, all acft depg to the W turn S ovr the water as soon as practical.**AIRPORT REMARKS:** Attended 1300-dusk. Parachute Jumping. Birds and deer on and invof arpt. Rwy 10 apch area has two 70' lgtd obstruction poles 170' left of cntrln; +75' trees on N side. Rwy 28 apch area has lgtd obstruction poles, 165' left and 220' right of cntrln; 80' trees adj. Landing fee waived with minimum fuel purchase.**AIRPORT MANAGER:** 231-206-9333**WEATHER DATA SOURCES:** AWOS-3P 119.925 (231) 347-5231. Wind spd & drctn unrel btn 260°-280°.**COMMUNICATIONS:** CTAF/UNICOM 122.8® **MINNEAPOLIS CENTER APP/DEP CON** 134.6**CLEARANCE DELIVERY PHONE:** For CD ctc Minneapolis ARTCC at 651-463-5588.**RADIO AIDS TO NAVIGATION:** NOTAM FILE PLN.**POLLSTON (L) (L) VORTACW** 111.8 PLN Chan 55 N45°37.84' W84°39.85' 227° 16.2 NM to fld. 836/6W.

VOR unusable:

301°-339°

GCP has azm only, no DME at GCP

**HARRIETTA****EAGLES LANDING** (4Y9) 3 W UTC-5(-4DT) N44°18.47' W85°46.30'

GREEN BAY

993 NOTAM FILE LAN

**RWY 08-26:** 2200X100 (TURF) 0.8% up E**RWY 08:** Trees.**RWY 26:** Trees.**AIRPORT REMARKS:** Unattended. No snow removal. Rwy 08-26 rough & uneven. Lrg depression east of Rwy 26. Rwy 08-26 mkd with 3' yellow cones. 60' trees both sides of rwy 100' from rwy cntrln.**AIRPORT MANAGER:** 586-944-7101**COMMUNICATIONS:** CTAF 122.9**CLEARANCE DELIVERY PHONE:** For CD ctc Minneapolis ARTCC at 651-463-5588.**HARRISON****CLARE CO** (8ØD) 2 NW UTC-5(-4DT) N44°03.14' W84°48.79'

LAKE HURON

1142 B NOTAM FILE LAN

**RWY 05-23:** 3000X100 (TURF)**RWY 05:** Trees.**RWY 23:** Thld dsplcd 800'. Road.**RWY 18-36:** H2978X50 (ASPH) LIRL(NSTD)**RWY 18:** Thld dsplcd 465'. Tree.**RWY 36:** Thld dsplcd 1160'. Tree.**RWY 09-27:** 2403X100 (TURF)**RWY 09:** Thld dsplcd 1196'. Tree.**RWY 27:** Thld dsplcd 837'. Tree.**SERVICE:** LGT ACTIVATE NSTD LIRL—CTAF. Rwy 18-36 NSTD LIRL due to improper color and lctn.**AIRPORT REMARKS:** Unattended. Deer & lrg birds on & invof arpt. Rwy 09-27 and Rwy 05-23 CLOSED Nov-Mar and when snow covd exc for ski equipped acft. Rwy 18-36 extsv cracking. Rwy 09-27 and dthr mkd with 3 ft yellow cones. Rwy 09-27 intmt patches of misg turf thrut full len & wid. Rwy 05-23 and dthr mkd with 3 ft yellow cones. Rwy 05 dthr 1700 ft, extds byd rwy midpt. Rwy 05-23 intmt patches of misg turf thrut full len & wid.**AIRPORT MANAGER:** 989-862-5333**COMMUNICATIONS:** CTAF/UNICOM 122.8**CLEARANCE DELIVERY PHONE:** For CD ctc Minneapolis ARTCC at 651-463-5588.