```
CLE ELUM
```

CLE ELUM MUNI (S93) 1 E UTC-8(-7DT) N47°11.65′ W120°53.04′ SEATTLE 1945 B NOTAM FILE SEA RWY 07-25: H2379X60 (ASPH) MIRI 0.3% up W RWY 07: REIL. PAPI(P2L)-GA 4.0° TCH 20'. Rgt tfc. RWY 25: REIL. PAPI(P2L)—GA 4.0° TCH 20'. SERVICE: LGT PAPI Rwy 07 and Rwy 25 opr continuously. ACTIVATE rotating bcn, MIRL Rwy 07-25 and REIL Rwy 07 and Rwv 25-CTAF. AIRPORT REMARKS: Unattended. Wildlife on and invof rwy. Gliders use CTAF freq 122.3. AIRPORT MANAGER: 509-674-2262 COMMUNICATIONS: CTAF 122 9 CLEARANCE DELIVERY PHONE: For CD ctc Seattle ARTCC at 253-351-3694. - - - - - - - - - - -**DE VERE FLD** (2W1) 3 E UTC-8(-7DT) N47°10.65′ W120°51.16′ SFATTI F 1800 NOTAM FILE SEA RWY 08-26: H2055X30 (ASPH) RWY 08: Trees. Rgt tfc. RWY 26: Trees. AIRPORT REMARKS: Attended dalgt hrs. Fld occasionally CLOSED in winter. Wildlife on and invof rwy. Rwy 08-26 has 2 inch dropoff along entr rwy both sides. Rwy 08-26 svr unsealed cracks and joints. Rwy 08-26 NSTD mrkgs no nrs, small and square aiming points painted on rwy ends. All patterns to the south. Rwy 08-26 mrkgs faded. AIRPORT MANAGER: 509-962-2066 COMMUNICATIONS: CTAF 122.9 CLEARANCE DELIVERY PHONE: For CD ctc Seattle ARTCC at 253-351-3694. **COLFAX LOWER GRANITE STATE** (ØØW) 12 S UTC-8(-7DT) N46°40.37′ W117°26.50′ SFATTI F 719 NOTAM FILESFA RWY 14-32: 3400X50 (GRVL) 0.9% up SE RWY 14: Trees. RWY 32: Hill. AIRPORT REMARKS: Unattended. Do not land if snow present on rwy. No winter snow removal ops. Pedestrians, vehicles and animals on and invof rwy. Ctc WA State Aviation Division 360-709-8015 or 1-800-552-0666 WA area for facility info prior to use. For acft accidents/incidents ctc WA state emergency operations center 800-258-5990. Ck density altitude. Gravel portions of rwy sfc rough and soft. Rwy marked with reflectors dur dates arpt is open. Steep drop off on both sides of runway. AIRPORT MANAGER: (360) 618-2477 COMMUNICATIONS: CTAF 122.9 CLEARANCE DELIVERY PHONE: For CD ctc Seattle ARTCC at 253-351-3694. PORT OF WHITMAN BUSINESS AIR CENTER (S94) 3 SW UTC-8(-7DT) N46°51.52′ W117°24.84′ SEATILE I_13R 2181 B TPA-3010(829) NOTAM FILE SEA RWY 08-26: H3209X60 (ASPH) S-17 MIRL 1.0% up E RWY 08: Thid dsplcd 492'. Road. RWY 26: Thid dsplcd 450'. Hill. RUNWAY DECLARED DISTANCE INFORMATION RWY 08: TORA-3209 TODA-3209 ASDA-3209 LDA-2718 RWY 26: TORA-3209 TODA-3209 ASDA-3209 LDA-2890 SERVICE: LGT ACTIVATE MIRL Rwy 08-26-CTAF. AIRPORT REMARKS: Attended May-Sept dawn-dusk, Oct-Apr, Mon-Fri dawn-dusk. Deer invof rwy. Watch for birds invof creek south of arpt. Rwy 08-26 farm machinery may be opr in flds on both sides of rwy and off both rwy ends. 30' bldg 250' south AER 26. Dense agricultural ops Feb-Oct. AIRPORT MANAGER: 509-397-2061 COMMUNICATIONS: CTAF/UNICOM 122 8 CLEARANCE DELIVERY PHONE: For CD ctc Seattle ARTCC at 253-351-3694. RADIO AIDS TO NAVIGATION: NOTAM FILE PUW. PULLMAN (VL) (L) VORW/DME 117.15 PUW Chan 118(Y) N46°40.45′ W117°13.41′ 305° 13.6 NM to fld. 2772/20E. DME unmonitored. DMF unusable: 040°-045° byd 35 NM blo 8,000′

065°-070° bvd 30 NM blo 7.000 090°-095° byd 35 NM blo 7,000°

VOR unusable: 032°-100° byd 40 NM 155°-195° byd 40 NM