




LOC/DME I-DDV 110.1 Chan 38	APP CRS 052°	Rwy Idg 12102 TDZE 736 Apt Elev 744
---	------------------------	--

ILS RWY 5R (SA CAT I)

RICKENBACKER INTL (LCK)

A Procedure NA when using John Glenn Columbus Intl altimeter setting. Requires specific OPSEC, MSPEC or LAO approval and use of HUD to DH.	ALSIF-2 	MISSED APPROACH: Climb to 1500 then climbing right turn to 3000 direct XUB VOR and hold.
---	-------------	--

ATIS 132.75	COLUMBUS APP CON 134.0 279.6	RICK TOWER 120.05 348.4	GND CON 125.275 275.8	CLNC DEL 125.275 275.8
-----------------------	--	-----------------------------------	---------------------------------	----------------------------------



CATEGORY	A	B	C	D
S-ILS 5R	RA 150/14 150 DA 886			

SA CATEGORY I ILS - SPECIAL AIRCREW & AIRCRAFT CERTIFICATION REQUIRED

TDZ/CL Rwy 5R
REIL Rwy 23R
HIRL Rwys 5L-23R and 5R-23L

EC-2, 28 MAR 2019 to 25 APR 2019

EC-2, 28 MAR 2019 to 25 APR 2019