

SEELEY LAKE (23S) 2 E UTC-7(-6DT) N47°10.92' W113°26.71'
 4256 B NOTAM FILE GTF
RWY 16-34: 4575X75 (TURF) 1.7% up NW

GREAT FALLS

RWY 16: Trees.

SERVICE: LGT Non-standard solar Rwy 34 – first 1/2 of rwy – summer months only.

AIRPORT REMARKS: Unattended. Birds and wildlife on and in/ovf arpt. Snow removal intermittent, call arpt mgr for current cond 406-444-2506. Tkfs to north not recommended due to rising terrain. Rwy 34 has 1150' overrun avbl for tkf and ldg. Trees in transitional sfc full rwy length both sides. Rwy 16-34 marked full length with white cones with reflective tape, summer months only. Crew car available.

AIRPORT MANAGER: 406-444-2506

COMMUNICATIONS: CTAF 122.9

SHELBY (SBX)(KSBX) 2 N UTC-7(-6DT) N48°32.44' W111°52.28'
 3443 B NOTAM FILE GTF
RWY 05-23: H5005X75 (ASPH) S-15 PCN 6 F/D/Y/T MIRL

GREAT FALLS

H-1D, L-13C

IAP

0.5% up NE

RWY 23: Road.

RWY 11-29: H3701X60 (ASPH) S-15 MIRL

SERVICE: FUEL 100LL, JET A+ LGT ACTIVATE MIRL Rwy 05-23 and Rwy 11-29—CTAF.

AIRPORT REMARKS: Attended 1500-0100Z±. For fuel after hrs call 406-450-2461 or 406-450-2463. Self svc credit card for 100LL and Jet A+. Fuel truck avbl for Jet A+. Cold temperature restricted airport. Altitude correction required at or below -31C. Deer on and in/ovf arpt. Twy edges marked with reflectors.

AIRPORT MANAGER: (406) 450-2463

COMMUNICATIONS: CTAF/UNICOM 122.8


CUT BANK RCO 122.2 (GREAT FALLS RADIO)

SALT LAKE CENTER APP/DEP CON 133.4

RADIO AIDS TO NAVIGATION: NOTAM FILE CTB.

CUT BANK (L) VORW/DME 113.35 CTB Chan 80(Y) N48°33.90'
 W112°20.60' 077° 18.9 NM to fld. 3791/17E.

NDB (MHW) 347 SBX N48°32.46' W111°51.75' at fld.
 3436/15E. NOTAM FILE GTF.



SHER-WOOD (See PLENTYWOOD on page 108)