

BELLINGHAM**BELLINGHAM INTL** (BLI)(KBLI) 3 NW UTC-8(-7DT) N48°47.56' W122°32.25'

171 B TPA—See Remarks AOE Class I, ARFF Index B NOTAM FILE BLI

RWY 16-34: H6700X150 (ASPH-GRVD) S-75, D-160, 2S-175, 2D-250

PCN 57 F/A/W/T HIRL

RWY 16: MALSR. PAPI(P4L)—GA 3.0° TCH 50'. RVR-T Rgt tfc.**RWY 34:** REIL. PAPI(P4L)—GA 3.0° TCH 50'. RVR-R**RUNWAY DECLARED DISTANCE INFORMATION****RWY 16:** TORA-6700 TODA-6700 ASDA-6700 LDA-6700**RWY 34:** TORA-6700 TODA-6700 ASDA-6700 LDA-6700**SERVICE:** S7 FUEL 100LL, JET A LGT When twr clsd ACTIVATE HIRL

Rwy 16-34, MALSR Rwy 16 and REIL Rwy 34—CTAF.

AIRPORT REMARKS: Attended continuously. Birds and coyotes on and invof arpt movement areas. PPR for unscheduled air carrier ops with more than 30 pax seats ctc ops at 360-739-1944. Twy A btn Twy E and Twy F clsd to acft winspan more than 118'. Portions of Twy A at Twy G and Twy J not vsbl from twr. Air carrier ops use Twy A, Twy B, Twy C, Twy D West of Twy E, Twy E, Twy F West of Twy A, Twy G, and Twy H. Coml ramp clsd to pvt acft. NS ABTMT procedures in effect ctc ops at 360-739-1944 or at www.flybli.com/noise. TPA-1200 (1030) fixed wing, 700(530) helicopter, 2000(1830) turbo. Ldg fee over 7,500 lbs. Flight Notification Service (ADCUS) avbl.

AIRPORT MANAGER: (360) 676-2500**WEATHER DATA SOURCES:** ASOS (360) 671-8688**COMMUNICATIONS:** CTAF 124.9 ATIS 134.45 360-647-5939 UNICOM 122.95


RCO 122.15 (SEATTLE RADIO)

Ⓡ VICTORIA TERMINAL APP/DEP CON 132.7

TOWER 124.9 (1500-0630Z‡) **GND CON** 127.4**AIRSPACE:** CLASS D svc 1500-0630Z‡; other times CLASS E.**RADIO AIDS TO NAVIGATION:** NOTAM FILE BLI.**WHATCOM (H) VORTACW** 113.0 HUH Chan 77 N48°56.72' W122°34.76' 150° 9.3 NM to fld. 82/20E. HIWAS.

TACAN AZIMUTH unusable:

155°-165° byd 15 NM blo 6,000'

ILS/DME 108.5 I-BLI Chan 22 Rwy 16. Class IA. ILS DME unusable beyond 30° left of course.**FLOATHAVEN SPB** (ØW7) 6 SE UTC-8(-7DT) N48°44.14' W122°20.40'

307 NOTAM FILE SEA

WATERWAY 12W-30W: 10000X4000 (WATER)**SERVICE:** S4

SEAPLANE REMARKS: Attended dalgth hrs. Canoe, sailboat, drone and hang glider activity invof arpt. For airframe repairs call 206-909-7299 prior to arrival to arrange svcs. Land and tkf in the center of the lake. Avoid flying over noise sensitive area during tkf and ldg.

AIRPORT MANAGER: 206-909-7299**COMMUNICATIONS:** CTAF 122.9

VICTORIA TERMINAL APP/DEP CON 132.7 290.8 604-586-4560

SEATTLE

BOEING FLD/KING CO INTL (See SEATTLE on page 220)**BOWERMAN** (See HOQUIAM on page 195)**BOWERS FLD** (See ELLENSBURG on page 189)