


HAVERHILL**DEAN MEM** (5B9) 3 NE UTC-5(-4DT) N44°04.81' W72°00.47'

582 NOTAM FILE BGR

RWY 01-19: H2511X58 (ASPH) S-8.5 LIRL(NSTD) 1.4% up S**RWY 01:** Thld dspicd 185'. Trees.**RWY 19:** Bldg.**SERVICE:** **FUEL** 100LL **LGT** ACTIVATE LIRL Rwy 01-19 and
windsock—CTAF.**AIRPORT REMARKS:** Attended irregularly. For winter conditions call
603-738-4158 24 hrs before use. Rwy 01-19 NSTD spacing, first
185' Rwy 01 not lgtd.**AIRPORT MANAGER:** (603) 787-6800**COMMUNICATIONS:** CTAF/UNICOM 122.8**BOSTON CENTER APP/DEP CON** 135.7**CLEARANCE DELIVERY PHONE:** For CD ctc Boston ARTCC at 603-879-6859.**RADIO AIDS TO NAVIGATION:** NOTAM FILE MPV.**MONTPELIER (L) VOR/DME** 110.8 MPV Chan 45 N44°05.13'
W72°26.96' 107° 19.1 NM to fld. 2080/16W.**MONTREAL****L-32H****IAP****HAWTHORNE-FEATHER AIRPARK** (See HILLSBORO on page 147)**HILLSBORO****HAWTHORNE-FEATHER AIRPARK** (8B1) 3 S UTC-5(-4DT) N43°03.68' W71°54.32'

600 B NOTAM FILE BGR

RWY 02-20: H3260X75 (ASPH) S-8 MIRL**RWY 02:** Trees.**RWY 20:** Trees. Rgt tfc.**SERVICE:** **FUEL** 100LL **LGT** Rwy lgts and rotating bcn OTS indef.
ACTIVATE MIRL Rwy 02-20—CTAF.**AIRPORT REMARKS:** Unattended. Prior to using arpt call 603-588-6868 for
arpt conditions. Self serve fuel avbl 24 hrs by credit card system.Wildlife on and in/ov arpt. Rwy sfc uneven with large open cracks. Rwy
02 markings faded and NSTD. Rwy 20 markings faded.**AIRPORT MANAGER:** 603-588-6868**COMMUNICATIONS:** CTAF/UNICOM 122.8**CLEARANCE DELIVERY PHONE:** For CD ctc Boston Arpt at 603-594-5551.**RADIO AIDS TO NAVIGATION:** NOTAM FILE CON.**CONCORD (L) VOR/DME** 112.9 CON Chan 76 N43°13.19'
W71°34.53' 252° 17.3 NM to fld. 715/15W. **HIWAS.****VORTAC** unusable:

022°-032° byd 20 NM blo 8,000'

190°-210° byd 12 NM blo 4,000'

318°-326° byd 30 NM blo 12,000'

DME unusable:

022°-032° byd 20 NM blo 8,000'

082°-110° byd 30 NM blo 5,000'

290°-300° byd 30 NM blo 7,000'

NEW YORK**L-32H, 33B**