

CAMPBELL FLD (See WEIRWOOD on page 388)**CAPE CHARLES** N37°20.85' W75°59.86' NOTAM FILE DCA.**(L) VORTAC** 112.2 CCV Chan 59 042° 21.2 NM to Accomack Co. 10/10W.

TACAN AZIMUTH unusable:

005°-015° byd 20 NM blo 4,000'

VOR unusable:

137°-322° byd 17 NM blo 2,000'

137°-322° byd 22 NM blo 3,000'

DME unusable:

005°-015° byd 20 NM blo 4,000'

RCO 122.1R 112.2T (LEESBURG RADIO)

WASHINGTON

H-101, 12H, L-35D, 36I

CASANOVA N38°38.47' W77°51.93' NOTAM FILE DCA.**(H) VORTAC** 116.3 CSN Chan 110 184° 6.9 NM to Culpeper Rgnl. 442/6W.

VOR unusable:

310°-350° byd 10 NM blo 11,000'

TACAN AZIMUTH unusable:

310°-350° byd 10 NM blo 11,000'

DME unusable:

310°-350° byd 10 NM blo 11,000'

RCO 122.1R 116.3T (LEESBURG RADIO)

WASHINGTON

H-10H, L-29D, 34E, 36I, A

CAVERNS N38°41.96' W78°28.34' NOTAM FILE DCA.**NDB (MHW)** 245 LUA 223° 2.4 NM to Luray Caverns. 834/9W. NDB unmonitored when arpt unatndd.

NDB unusable:

050°-208° byd 10 NM

209°-049° byd 15 NM

WASHINGTON

L-29G

CHAMBERS FLD (See NORFOLK NS (CHAMBERS FLD) on page 371)**CHARLOTTESVILLE-ALBEMARLE** (CHO)(KCHO) 7 N UTC-5(-4DT) N38°08.38'

W78°27.14'

640 B Class I, ARFF Index B NOTAM FILE CHO MON Airport

RWY 03-21: H6801X150 (ASPH-GRVD) S-120, D-228, 2S-175,

2D-368 PCN 65 F/C/X/T HIRL 0.3% up SW

RWY 03: MALSR.**RWY 21:** REIL. PAPI(P4R)—GA 3.0° TCH 50'.**RUNWAY DECLARED DISTANCE INFORMATION****RWY 03:** TORA-6801 TODA-6801 ASDA-6801 LDA-6801**RWY 21:** TORA-6801 TODA-6801 ASDA-6801 LDA-6801**SERVICE:** S4 FUEL 100LL, JET A LGT Rwy 21 PAPI unusable byd 6.5°

left of RCL. When twr clsd HIRL Rwy 03-21, and twy lgts preset low

ints. To ACTIVATE and increase intensity MALSR Rwy 03, REIL Rwy

21, HIRL Rwy 03-21 and twy lgts—CTAF.

AIRPORT REMARKS: Attended 0930-0530Z†. Deer and birds on and infov

arpt. PPR 8 hrs for unscheduled air carrier ops with more than 9

passenger seats between 0400-1100Z†, call arpt manager

434-981-4152. Wheeled helicopters are requested to ground taxi

when transiting arpt. Twy J uncontrolled, not visible from twr. Ldg fee

only for acft over 7000 lbs.

AIRPORT MANAGER: 434-973-8342**WEATHER DATA SOURCES:** ASOS (434) 973-5024**COMMUNICATIONS:** CTAF 124.5 ATIS 118.425 UNICOM 122.95**RCO** 122.2 122.65 (LEESBURG RADIO)® **POTOMAC APP/DEP CON** 132.85

APP/DEP CON 120.525

TOWER 124.5 (1100-0400Z†) **GND CON** 121.9**CLEARANCE DELIVERY PHONE:** For CD when ATCT is clsd ctc Potomac Apch at 866-640-4124.**AIRSPACE:** CLASS D svc 1100-0400Z†; other times CLASS E.**RADIO AIDS TO NAVIGATION:** NOTAM FILE DCA.**GORDONSVILLE (H) VORTAC** 115.6 GVE Chan 103 N38°00.82' W78°09.18' 304° 16.1 NM to fld. 383/6W.

HIWAS.

TACAN AZIMUTH unusable:

250°-260° byd 25 NM blo 7,000'

ILS/DME 111.7 I-CHO Chan 54 Rwy 03. Class IA. ILS unmonitored when ATCT closed.

WASHINGTON

H-10H, 12I, L-26I, 36H

IAP, AD

