

DICKINSON — THEODORE ROOSEVELT RGNL (DIK)(KDIK) 5 S UTC-7(-6DT) N46°47.84' W102°48.11'

BILLINGS
H-2H, L-14F
IAP, AD

2592 B TPA—See Remarks Class I, ARFF Index A NOTAM FILE DIK

RWY 14-32: H6399X100 (ASPH-GRVD) S-30, D-37.5

PCN 12 F/D/W/T MIRL

RWY 14: REIL. VASI(V4L)—GA 3.0° TCH 44'. Road.

RWY 32: MALSR. VASI(V4L)—GA 3.0° TCH 55'.

RWY 07-25: H4700X75 (ASPH-GRVD) S-16, D-20 PCN 5 F/D/W/T

MIRL 0.4% up E

RWY 07: REIL. PAPI(P2L)—GA 3.0° TCH 28'.

RWY 25: REIL. PAPI(P2L)—GA 3.0° TCH 28'. Road.

RUNWAY DECLARED DISTANCE INFORMATION

RWY 07: TORA-4700 TODA-4700 ASDA-4700 LDA-4700

RWY 14: TORA-6399 TODA-6399 ASDA-6399 LDA-6399

RWY 25: TORA-4700 TODA-4700 ASDA-4700 LDA-4700

RWY 32: TORA-6399 TODA-6399 ASDA-6399 LDA-6399

SERVICE: S4 FUEL 100LL, JET A LGT MIRL Rwys 07-25 and 14-32 preset on low ints dusk-0500Z‡; to increase ints after 0500Z‡ and ACTIVATE PAPI Rwy 07 and 25 and VASI Rwy 14 and Rwy 32, REIL Rwy 14, Rwy 07 and 25 and MALSR Rwy 32—CTAF.

AIRPORT REMARKS: Attended 1400-2300Z‡. For svc after hrs call

701-264-9966. Contact arpt manager for weight restriction waiver

701-483-1062. Birds on and invof arpt. Aflid sfc conditions not monitored between the hrs of 23:00 and 04:30 local

time. Cold temperature restricted arpt. Altitude correction required at or below -30C. Haying operations adjacent to all surfaces Jun-Sep. Rwy 07-25 not avbl for acft opns utilizing acft with more than 9 psgr seats. Crop dusting operations invof arpt. PAEW on movement areas during winter (Oct-Apr). TPA—single engine 3602 (1010); multiengine 4102 (1510). Conc apron for heavy acft parking. CAUTION: unlit tower 295.9' AGL (3045.9' MSL), 20.5 NM west northwest of airport.

AIRPORT MANAGER: 701-483-1062

WEATHER DATA SOURCES: ASOS 118.375 (701) 227-0280.

COMMUNICATIONS: CTAF/UNICOM 123.0

RCO 122.2 (GRAND FORKS RADIO)

MINNEAPOLIS CENTER APP/DEP CON 124.25

CLEARANCE DELIVERY PHONE: For CD if una to ctc on FSS freq, ctc Minneapolis ARTCC at 651-463-5588.

AIRSPACE: CLASS E.

RADIO AIDS TO NAVIGATION: NOTAM FILE DIK.


(H) VORTACW 112.9 DIK Chan 76 N46°51.60' W102°46.41' 183° 3.9 NM to fld. 2527/14E.

VOR unusable:

260°-270°

NOSON NDB (MHW) 353 DI N46°41.29' W102°42.74' 321° 7.5 NM to fld. 2630/10E.

ILS 108.3 I-DIK Rwy 32. Class IT. LOM NOSON NDB. Glideslope unusable byd 4° left of LOC course.



DRAYTON MUNI (D29) 3 N UTC-6(-5DT) N48°37.11' W97°10.55'

TWIN CITIES

798 B NOTAM FILE GFK

RWY 17-35: H2596X60 (ASPH) S-4 LIRL

RWY 35: Thld dsplcd 505'.

SERVICE: LGT LIRL Rwy 17-35 opr dusk-0600Z‡, after 0600Z‡, ACTIVATE LIRL Rwy 17-35 —CTAF.

AIRPORT REMARKS: Unattended. For svc call 701-454-6588. Confirm winter conditions and snow removal before use, call 701-454-3590 or 701-454-6588. Rwy 35 dsplcd thld ngt ops only.

AIRPORT MANAGER: 701-520-1219

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Minneapolis ARTCC at 651-463-5588.

DUNN CO WEYDAHL FLD (See KILLDEER on page 336)