

SKANEATELES AERO DROME (6B9) 2 SW UTC-5(-4DT) N42°54.84' W76°26.45'

NEW YORK

1039 TPA-1839(800) NOTAM FILE BUF

L-32F

RWY 04-22: 3350X130 (TURF) 0.8% up SW

IAP

RWY 04: Trees.**RWY 22:** Fence.**RWY 10-28:** H3134X58 (ASPH) S-9 MIRL(NSTD) 0.4% up W**RWY 10:** Thld dspcd 243'. Trees.**RWY 28:** Trees.**SERVICE:** FUEL 100LL LGT Arpt lgt OTS indef. ACTIVATE MIRL Rwy 10-28—CTAF.

AIRPORT REMARKS: Unattended, call manager. Fuel avbl 24 hr self svc credit card. Rwy 28 two 55' power poles 70' either side centerline 700' from thld. Rwy 04-22 avbl 15 May to 15 Oct. Rwy 10-28 NSTD MIRL, lghts are 38' from pavement edge. Rwy 28 has 4 lghts out and 2 lghts very dim. One thld lgt is rotated 90° (red/green lens). Rwy 10 3' fence 20' from thld on both sides, 15' road 30' from thld on both sides and 4' fence 80' from thld on both sides. -10' culvert/ditch 50' left of centerline at thld. Rwy 04-22 has variations in rwy sfc.

AIRPORT MANAGER: 707-580-9240**WEATHER DATA SOURCES:** AWOS-3P 120.125 (315) 685-5790.**COMMUNICATIONS:** CTAF/UNICOM 122.8Ⓡ **SYRACUSE APP/DEP CON** 126.125**CLEARANCE DELIVERY PHONE:** For CD ctc Syracuse Apch at 315-455-6218.**RADIO AIDS TO NAVIGATION:** NOTAM FILE SYR.**SYRACUSE (H) VORTACW** 117.0 SYR Chan 117 N43°09.63' W76°12.27' 226° 18.1 NM to fld. 453/11W.

TACAN AZIMUTH & DME unusable;


Byd 35 NM blo 4,000'

VOR unusable:

010°-025°

067°-077° byd 30 NM

134°-144° byd 19 NM

**SKY ACRES** (See MILLBROOK on page 216)**SKY PARK** (See RED HOOK on page 234)**SOUTH ALBANY** (See SOUTH BETHLEHEM on page 242)**SOUTH BETHLEHEM****SOUTH ALBANY** (4BØ) 2 N UTC-5(-4DT) N42°33.64' W73°50.04'

NEW YORK

196 NOTAM FILE BTV

L-32G, 33B, 34I

RWY 01-19: H2853X60 (ASPH) LIRL 0.4% up N

IAP

RWY 01: RVR-T Thld dspcd 150'. Fence.**RWY 19:** RVR-R Thld dspcd 124'. Road.**SERVICE:** S4 FUEL 100LL, JET A LGT ACTIVATE LIRL Rwy 01-19 and windsock lgt—CTAF.

AIRPORT REMARKS: Attended Nov-Mar 1300-2100Z†, Apr-Oct 1100-0200Z‡. Arpt clsd to acct over 12,500 lbs. Birds on and invof arpt. Helicopter NS ABTMT procedures in effect. VFR dep maintain rwy hdg until reaching 500' AGL. Avoid arr and dep to/from the west. +17' railroad across centerline 200' S of Rwy 01.

AIRPORT MANAGER: (518) 281-5430**COMMUNICATIONS:** CTAF 122.9Ⓡ **ALBANY APP/DEP CON** 118.05**CLEARANCE DELIVERY PHONE:** For CD ctc Albany Apch at 518-862-2299.**RADIO AIDS TO NAVIGATION:** NOTAM FILE BTV.**CAMBRIDGE (L) VOR/DME** 115.0 CAM Chan 97 N42°59.66' W73°20.64' 234° 33.8 NM to fld. 1490/14W.

DME portion unusable:

040°-130° blo 9,000'