

CUMBERLAND


GREATER CUMBERLAND RGNL (CBE)(KCBE) 2 S UTC-5(-4DT) N39°36.92' W78°45.69'

WASHINGTON
H-10H, 12I, L-29D
IAP

775 B TPA—1799(1024) NOTAM FILE EKN
RWY 05-23: H5047X150 (ASPH) S-38, D-52 HIRL 1.1% up NE
RWY 05: Trees. Rgt tfc.
RWY 23: REIL. PAPI(P4L)—GA 3.59° TCH 29'.
RWY 11-29: H3000X150 (ASPH) S-12 LIRL(NSTD)
RWY 11: Thld dsplcd 560'. Hill.
RWY 29: Tree.

SERVICE: S4 FUEL 100LL, JET A OX 1, 2, 3, 4 LGT ACTIVATE HIRL
 Rwy 05-23, LIRL Rwy 11-29, REIL Rwy 23 and twy lgts—CTAF. Rwy 11 NSTD LIRL thld to Rwy 11 dsplcd thld, due to improper lens colors and spacing.

AIRPORT REMARKS: Attended 1300-0100Z†. Bottle oxygen avbl from 1300-2000Z† Mon-Fri by prior arrangement, call 304-738-0002 ext 11. Bulk oxygen avbl from 1300-2000Z† Mon-Fri by prior arrangement, call 304-738-0002 ext 11. Glider ops west of arpt use Rwy 11 for departure, Rwy 29 for arrival. Rwy 05 apch has rapidly rising terrain 696' left, 2000' from thld. Rwy 11 ngt ops and any llds not recommended due to high terrain. Deer/birds on and invof arpt. Rwy 23 900' twy aligned with rwy west end. Rotating bcn located off arpt. Rwy 05-23 markings and CL partially obscured by longitudinal and transverse crack fill. Rwy 05-23 markings faded. Cold temperature airport. Altitude correction required at or below -15C.



AIRPORT MANAGER: 304-738-0002

WEATHER DATA SOURCES: AWOS-3 128.625 (304) 738-0451.

COMMUNICATIONS: CTAF/UNICOM 122.8

CUMBERLAND RCO 122.35 (ELKINS RADIO)

Ⓡ **JOHNSTOWN APP/DEP CON** 121.2 (1200-0400Z†)

Ⓡ **CLEVELAND CENTER APP/DEP CON** 124.4 (0400-1200Z†)

CLEARANCE DELIVERY PHONE: For CD ctc Johnstown Apch at 814-532-5960, when Apch clsd ctc Cleveland ARTCC at 440-774-0234.

RADIO AIDS TO NAVIGATION: NOTAM FILE EKN.

GRANTSVILLE (L) DME 112.3 GRV Chan 70 N39°38.10' W79°03.03' 095° 13.5 NM to fld. 2640/OW.

DME unusable:

071°-306° byd 20 NM blo 6,000'

108°-113° byd 38 NM

307°-070° byd 20 NM blo 5,000'

325°-345° byd 35 NM

LOC/DME 110.5 I-CBE Chan 42 Rwy 23. DME unusable byd 22° left of course. DME unusable byd 10 NM blw 3,500'.

MEXICO FARMS (1W3) 3 S UTC-5(-4DT) N39°36.32' W78°45.65'

WASHINGTON

607 TPA—1407(800) NOTAM FILE EKN

RWY 09-27: 2120X190 (TURF) LIRL

RWY 09: Trees. Rgt tfc.

RWY 27: Thld dsplcd 340'. Trees.

RWY 16-34: 2100X195 (TURF)

RWY 16: Brush.

RWY 34: Thld dsplcd 800'. Tree.

SERVICE: LGT ACTIVATE LIRL Rwy 09-27—122.8.

AIRPORT REMARKS: Unattended. Rwy 16-34 CLOSED indef. Ultralight activity on and invof arpt. Wildlife on and invof arpt. Rising terrain 4500' west of arpt. Rwy 09-27, and 16-34 may be soft. Rwy 27 dsplcd thld marked with cones on both sides.

AIRPORT MANAGER: 301-724-5231

COMMUNICATIONS: CTAF/UNICOM 122.8

CLEARANCE DELIVERY PHONE: For CD ctc Johnstown Apch at 814-532-5960, when Apch clsd ctc Cleveland ARTCC at 440-774-0234.

DAVIS (See LAYTONSVILLE on page 102)