

DANVILLE (8N8) 3 SW UTC-5(-4DT) N40°56.90' W76°38.64'
559 B NOTAM FILE IPT
RWY 09-27: H3000X60 (ASPH) MIRL 0.4% up E

RWY 09: Trees.

RWY 27: Trees.

SERVICE: S4 LGT Lighting NSTD. ACTVT MIRL Rwy 09-27 drg periods of darkness only—CTAF. Rwy 27 thld lgts dsplcd 365' from rwy end for ngt displacement. Rwy end lgtd with two red lgts on left side (NSTD).

AIRPORT REMARKS: Attended irregularly. After hrs ctc 570-274-6190. Deer and wildlife on and invof arpt. Radio controlled airplane ops N of rwy. Main ramp no prop wash invof main hangar due to acft painting.

AIRPORT MANAGER: 570-274-6190

COMMUNICATIONS: CTAF/UNICOM 122.8


Ⓜ WILKES-BARRE APP/DEP CON 126.3

CLEARANCE DELIVERY PHONE: For CD ctc Wilkes-Barre Apch at 570-655-2084.

RADIO AIDS TO NAVIGATION: NOTAM FILE IPT.

MILTON (L) VORTACW 109.2 MIP Chan 29 N41°01.40'
W76°39.92' 177° 4.6 NM to fld. 1000/9W.

NEW YORK
L-30J
IAP



DECK (See MYERSTOWN on page 292)

DONEGAL SPRINGS AIRPARK (See MOUNT JOY/MARIETTA on page 290)

DOVER

LAZY B RANCH (ØP8) 3 E UTC-5(-4DT) N40°01.47' W76°48.92'
476 NOTAM FILE IPT

RWY 05-23: H2400X60 (ASPH-CONC) LIRL 1.3% up SW

RWY 05: Brush.

RWY 23: Tree.

SERVICE: LGT For LIRL Rwy 05-23 key 122.9 five times.

AIRPORT REMARKS: Unattended. Ctc arpt manager 717-292-7029. Deer invof arpt. Turf area parallel to Rwy 05-23, for taxi only, marked with yellow cones.

AIRPORT MANAGER: 717-332-9233

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Harrisburg Apch at 800-932-0712.

NEW YORK