

STELLAR AIRPARK (P19) 3 W UTC-7 N33°17.93' W111°54.95'
1179 B TPA-2002(823) NOTAM FILE PRC

PHOENIX
L-5B, A
IAP

RWY 17-35: H4417X80 (ASPH) MIRL

RWY 17: REIL. PAPI(P2L)—GA 3.25° TCH 39'. Thld dsplcd 366'.
Road.

RWY 35: REIL. PAPI(P2R)—GA 3.25° TCH 40'. Thld dsplcd 349'. Tree.

RUNWAY DECLARED DISTANCE INFORMATION

RWY 17: LDA-4050

RWY 35: LDA-4067

SERVICE: S2 FUEL 100LL LGT ACTVT REIL Rwy 17 and Rwy 35; MIRL
Rwy 17-35—CTAF.

AIRPORT REMARKS: Unattended. For fuel and tiedown information ctc FBO at (480) 961-9050. Birds on or invof arpt. Be alert to numerous no radio aircraft invof arpt. PPR rqrd for acct certificated for 15,000 gross takeoff weight not based at arpt. Training arpt touch and go landing proh. Helicopter training proh. Commercial and student training ops by permit only. Practice instrument approaches in VFR conditions not authorized. Calm wind Rwy 17. All runups on east side runup areas. Avoid overflight of noise sensitive areas west of Rwy 17-35 and north of arpt. Flood irrigation between rwy and twy with standing water up to 1' depth on irregular schedule. Ldg fee charged for all commercial ops.

AIRPORT MANAGER: 480-295-2683

COMMUNICATIONS: CTAF/UNICOM 122.975

Ⓡ PHOENIX APP/DEP CON 123.7

CLEARANCE DELIVERY PHONE: For CD ctc Phoenix Apch at 602-306-2565.

RADIO AIDS TO NAVIGATION: NOTAM FILE PRC.

PHOENIX (H) VORTACW 115.6 PXR Chan 103 N33°25.98' W111°58.21' 149° 8.5 NM to fld. 1184/12E.

VOR unusable:

345°-360° byd 33 NM blo 10,000'

TACAN AZIMUTH & DME unusable:

345°-360° byd 33 NM blo 11,000'

VORTAC unusable:

015°-034° byd 33 NM blo 10,000'

090°-100° byd 15 NM blo 8,000'

185°-190° byd 30 NM blo 8,000'

185°-190° byd 38 NM blo 9,000'

190°-230° byd 20 NM blo 10,000'

345°-034° byd 10 NM blo 6,000'

345°-034° byd 20 NM blo 8,000'

360°-015° byd 33 NM blo 11,000'

DME unusable:

215°-315°



CHINLE MUNI (E91) 3 SW UTC-7 N36°06.56' W109°34.53'

5550 B NOTAM FILE PRC

DENVER
H-4K, L-8H

RWY 18-36: H6902X60 (ASPH) S-12.5 MIRL 0.3% up S

RWY 36: PAPI(P2L).

SERVICE: LGT ACTIVATE PAPI Rwy 36; MIRL Rwy 18-36—CTAF.

AIRPORT REMARKS: Unattended. Call Navajo Hospital Security at 928-283-2842 to start generator for beacon and rwy lggt at night and during inclement weather. Gate code: 5550. Drive time to arpt is 10 minutes. Rwy 18-36 1-9 inch wide longitudinal and transverse cracks entire length. Large cracks and loose aggregate in parking apron. Rwy 36 numbers faded.

AIRPORT MANAGER: (505) 728-2804

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Denver ARTCC at 303-651-4257.

RADIO AIDS TO NAVIGATION: NOTAM FILE GUP.

GALLUP (H) VORTAC 115.1 GUP Chan 98 N35°28.56' W108°52.36' 304° 51.2 NM to fld. 7053/14E.