

LEVEL ISLAND N56°28.06' W133°04.99' NOTAM FILE SIT.
(H) VORW/DME 116.5 LVD Chan 112 229° 19.3 NM to Point Baker. 98/20E.

JUNEAU
H-1C, L-1C

VOR unusable:

038°-098° byd 35 NM blo 9,000'
 098°-138° byd 25 NM blo 7,000'
 168°-208° byd 35 NM blo 6,000'
 268°-328° byd 25 NM blo 9,000'
 328°-358° byd 30 NM blo 7,000'
 328°-358° byd 35 NM blo 8,000'
 358°-038° byd 35 NM blo 12,000'

wx cam

DME unusable:

038°-098° byd 35 NM blo 9,000'
 098°-138° byd 25 NM blo 7,000'
 168°-208° byd 35 NM blo 6,000'
 268°-328° byd 25 NM blo 9,000'
 328°-358° byd 30 NM blo 7,000'
 328°-358° byd 35 NM blo 8,000'
 358°-038° byd 35 NM blo 12,000'

RCO 122.3 (SITKA RADIO)

LEVELOCK (9Z8) 1 NNW UTC-9(-8DT) N59°07.63' W156°51.59'
 56 B NOTAM FILE ENA

KODIAK
L-21, 3C

RWY 01-19: 3284X60 (GRVL-DIRT) MIRL

RWY 01: Brush.

RWY 19: Brush.

SERVICE: LGT ACTIVATE MIRL Rwy 01-19 and rotating bcn—CTAF.

AIRPORT REMARKS: Unattended. Rwy condition not monitored. Recommend visual inspection prior to ldg. Rwy 01-19 and shoulders soft and muddy when wet. Multiple 2"-4" ruts on rwy edges and circular ruts near rwy thlds. Windssocks in soft soil, may be unreliable. Safety areas byd thlds sinking soft sand use only as emergency overrun.

AIRPORT MANAGER: 907-246-3325

COMMUNICATIONS: CTAF 122.9 UNICOM 122.95

RADIO AIDS TO NAVIGATION: NOTAM FILE AKN.

KING SALMON (H) VORTAC 112.8 AKN Chan 75 N58°43.48'

W156°45.14' 336° 24.4 NM to fld. 95/16E.

TACAN antenna offset 150' se

TACAN AZIMUTH unusable:

130°-140° byd 13 NM blo 4,000'


130°-140° byd 30 NM

332°-348° byd 19 NM blo 5,000'

DME unusable:

332°-348° byd 19 NM blo 5,000'

COMM/NAV/WEATHER REMARKS: For a toll free call to Kenai FSS dial 1-866-864-1737.



LIME VILLAGE (2AK) 0 N UTC-9(-8DT) N61°21.55' W155°26.42'

MC GRATH

545 NOTAM FILE ENA

RWY 10-28: 1500X55 (GRVL-DIRT) 0.3% up E

RWY 10: Brush.

RWY 28: Brush.

AIRPORT REMARKS: Unattended. Rwy condition not monitored, recommend visual inspection prior to using. NW rwy end floods dur break-up. Thld panel Rwy 10 only. Rwy 10-28 marked with orange 3' cones. Rwy 10-28 irregular sfc loose rocks up to 12 in may be present length of runway. Windssock unreliable.

AIRPORT MANAGER: 907-524-3241

COMMUNICATIONS: CTAF 122.9

RADIO AIDS TO NAVIGATION: NOTAM FILE PASV.

SPARREVOHN (H) VORW/DME 117.2 SQA Chan 119 N61°05.91'

W155°38.07' 002° 16.7 NM to fld. 250/18E.

VOR & DME unusable:

009°-019°

029°-039° byd 25 NM blo 12,500'

DME portion unusable:

019°-028° byd 16 NM

VOR portion unusable:

019°-029° byd 16 NM

COMM/NAV/WEATHER REMARKS: or a toll free call to Kenai FSS dial 1-866-864-1737.

