

FALMOUTH AIRPARK (5B6) 4 NE UTC-5(-4DT) N41°35.14' W70°32.42'

NEW YORK

41 B NOTAM FILE BDR

RWY 07-25: H2298X40 (ASPH) S-4 LIRL

RWY 07: Trees. Rgt tfc.

RWY 25: Trees.

SERVICE: FUEL 100LL, UL94 LGT ACTVT LIRL Rwy 07-25-122.7.

AIRPORT REMARKS: Attended 1300-2100Z†. Wildlife invof arpt. Turf around Rwy 07-25 soft after rain. Be aware of hi-speed mtl jet and heavy helicopter tfc invof of Cape Cod CGAS. Airport clsd to act exceeding 5000 lbs published maximum gross weight. Tran ops daytime only. No ngt tran tkfs or ldfs. No tran student activities, solo or dual at Falmouth Airpark. Full stops only. Touch and go ops prohibited. Prop-locks rqrd for all acft remaining overnight.

AIRPORT MANAGER: 508-548-9617

COMMUNICATIONS: CTAF/UNICOM 122.8

Ⓡ BOSTON APP/DEP CON 118.2

CLEARANCE DELIVERY PHONE: For CD ctc Boston Apch at 603-594-5554.

FITCHBURG MUNI (FIT)(KFIT) 3 SE UTC-5(-4DT) N42°33.25' W71°45.54'

NEW YORK

348 B TPA-1350(1002) NOTAM FILE FIT

RWY 14-32: H4510X100 (ASPH) S-30, D-41 MIRL 0.3% up NW

RWY 14: VASI(V2L)-GA 4.0°. Trees.

RWY 32: REIL. Thld dspclcd 242'. Trees.

RWY 02-20: H3504X75 (ASPH) S-30, D-41 0.5% up N

RWY 02: Thld dspclcd 567'. Trees.

RWY 20: Thld dspclcd 459'. Trees.

SERVICE: S4 FUEL 100LL, JET A LGT ACTIVATE REIL Rwy 32, VASI Rwy 14, MIRL Rwy 14-32-123.0. Rotating bcn not avbl during dalgt IFR conditions.

AIRPORT REMARKS: Attended Apr-Sep 1300-0000Z†, Oct-Mar 1300-2200Z†. Rwy 02-20 clsd permly. Wildlife on and invof arpt. Cold temperature rstd arpt. Altitude correction required at or below -25C. Ldg fee for corporate and commercial flts only.

AIRPORT MANAGER: 978-345-9580

WEATHER DATA SOURCES: ASOS 135.175 (978) 343-9121.

COMMUNICATIONS: CTAF/UNICOM 122.7


RCO 122.15 (BRIDGEPORT RADIO)

Ⓡ BOSTON APP/DEP CON 124.4

RADIO AIDS TO NAVIGATION: NOTAM FILE BDR.

GARDNER (L) VOR/DME 110.6 GDM Chan 43 N42°32.76'

W72°03.49' 102° 13.3 NM to fld. 1280/14W.



GARDNER MUNI (GDM)(KGDM) 2 SW UTC-5(-4DT) N42°32.99' W72°00.96'

NEW YORK

954 B NOTAM FILE BDR

RWY 18-36: H3000X75 (ASPH) S-25 MIRL 1.0% up N

RWY 18: Trees.

RWY 36: Trees.

SERVICE: S2 FUEL 100LL LGT ACTIVATE MIRL Rwy 18-36-CTAF.

AIRPORT REMARKS: Attended irregularly. No radio acft on and invof arpt.

Wildlife on and in vnty of arpt.

AIRPORT MANAGER: 978-852-1331

COMMUNICATIONS: CTAF/UNICOM 122.8


RCO 122.1R 110.6T (BRIDGEPORT RADIO)

Ⓡ BOSTON CENTER APP/DEP CON 123.75

RADIO AIDS TO NAVIGATION: NOTAM FILE BDR.

(L) VOR/DME 110.6 GDM Chan 43 N42°32.76'

W72°03.49' 097° 1.9 NM to fld. 1280/14W.



GARDNER N42°32.76' W72°03.49' NOTAM FILE BDR.

NEW YORK

(L) VOR/DME 110.6 GDM Chan 43 097° 1.9 NM to Gardner Muni. 1280/14W.

H-11D, 12I, L-33C, 34J

RCO 122.1R 110.6T (BRIDGEPORT RADIO)