

PRINCETON (39N) 3 N UTC-5(-4DT) N40°23.95' W74°39.54'
 128 B NOTAM FILE MIV
RWY 10-28: H3499X75 (ASPH) S-15 MIRL
RWY 10: REIL. PAPI(P2L)—GA 3.45° TCH 42'. Tree.
RWY 28: PAPI(P2L)—GA 3.0° TCH 41'. Thld dsplcd 369'. Bldg.
SERVICE: S4 FUEL 100LL, JET A LGT ACTIVATE MIRL Rwy 10-28 and REIL Rwy 10—123.05.

AIRPORT REMARKS: Attended 1300-dusk. Unattended Christmas Day and New Years Day. Deer and birds on and in/ovf arpt. Rwy 28 departure no turns until at least 900' MSL and beyond Cherry Hill Road. Rwy 10-28 rgt t/c helicopters.

AIRPORT MANAGER: 609-921-3100

COMMUNICATIONS: CTAF/UNICOM 122.725

Ⓡ NEW YORK APP/DEP CON 132.8

CLEARANCE DELIVERY PHONE: For CD ctc New York ApcH at 800-645-3206

RADIO AIDS TO NAVIGATION: NOTAM FILE IPT.

YARDLEY (L) VOR/DME 108.2 ARD Chan 19 N40°15.20'
 W74°54.46' 062° 14.4 NM to fld. 294/10W.

VOR unusable:

020°-040°

195°-225° byd 25 NM blo 5,000'

250°-265° blo 3,500'


266°-280° byd 20 NM blo 5,000'

281°-300° byd 14 NM blo 6,000'

DME unusable:

225°-275° byd 25 NM blo 5,000'

NEW YORK
 L-34H
 IAP



RAINBOW N39°25.09' W75°08.10' NOTAM FILE MIV.
 NDB (HW) 363 RNB 147° 4.2 NM to Millville Muni. 92/11W.

WASHINGTON
 H-101, L-34G, A
 IAP

READINGTON

SOLBERG-HUNTERDON (N51) 1 NW UTC-5(-4DT) N40°34.96' W74°44.20'
 189 TPA—See Remarks NOTAM FILE MIV

RWY 04-22: H5598X50 (ASPH-TURF) MIRL 0.7% up NE

RWY 04: Thld dsplcd 1301'.

RWY 22: Thld dsplcd 1300'. Tree.

RWY 13-31: 3444X200 (TURF) 1.0% up NW

RWY 13: Tree.

RWY 31: Trees.

RWY 10-28: 2010X100 (TURF) 0.4% up W

RWY 10: Trees.

SERVICE: S4 FUEL 100LL, JET A OX 2

AIRPORT REMARKS: Attended 1400-2200Z†. Arpt unattended all major holidays and Christmas and New Years eve afternoons. Deer on and in/ovf arpt. Blimp and hot air balloon activity on and in/ovf arpt, spring through fall. Dsplcd thld Rwy 04 1301' turf, 180' wide. Dsplcd thld Rwy 22 1300' turf, 180' wide. All rwys no touch and go l/dgs. TPA—1194(1005) for piston acct and 1694(1505) for jet acct. All rwys depart straight out to 1200' before turning. Rwy 04-22 MIRL on paved 3000' X 50' portion of rwy. Tkofs and l/dgs prohibited on Rwy 04 when acct are operating on Rwy 13-31 and Rwy 10-28. Ctc ops, 908-534-4000, prior to operating on Rwy 10-28.

AIRPORT MANAGER: 908-534-4000

COMMUNICATIONS: CTAF/UNICOM 122.8

SOLBERG RCO 122.1R 112.9T (MILLVILLE RADIO)

Ⓡ NEW YORK APP/DEP CON 132.8


GCO 121.725 If unable, ctc NY ApcH at 800-645-3206.

RADIO AIDS TO NAVIGATION: NOTAM FILE MIV.

(L) **VOR/DME** 112.9 SBJ Chan 76 N40°34.98' W74°44.51' at fld. 189/10W.

DME unusable:

167°-040° byd 34 NM



NEW YORK
 H-101, 121, L-33A, 34H
 IAP

REDWING (See JOBSTOWN on page 158)