

COLUMBIA—MARION CO (ØRØ) 3 N UTC-6(-5DT) N31°17.82' W89°48.77'

265 B NOTAM FILE GW0

NEW ORLEANS

L-21B, 22F

IAP

RWY 05-23: H4460X70 (ASPH) S-30 MIRL 0.5% up NE

RWY 05: PAPI(P2L)—GA 3.0° TCH 40'. Trees.

RWY 23: REIL. PAPI(P2L)—GA 3.0° TCH 40'. Tree.

SERVICE: FUEL 100LL, JET A LGT ACTIVATE MIRL Rwy 05-23 and Rwy 23 PAPI—CTAF.

AIRPORT REMARKS: Attended on call. For svc call 601-441-0299 or 601-441-1867. Fuel svc avbl 24 hrs with credit card. PAEW. Pub phone avbl 601-736-9295. Courtesy car avbl.

AIRPORT MANAGER: 601-736-9295

WEATHER DATA SOURCES: AWOS-3PT 120.675 (601) 736-4983.

COMMUNICATIONS: CTAF/UNICOM 122.8

® **HOUSTON CENTER APP/DEP CON** 126.8

CLEARANCE DELIVERY PHONE: For CD ctc Houston ARTCC at 281-230-5622.

RADIO AIDS TO NAVIGATION: NOTAM FILE GW0.

EATON (L) VORTACW 110.6 LBY Chan 43 N31°25.12'

W89°20.26' 249° 25.5 NM to fld. 290/5E.

VORTAC unusable:

300°-000° byd 30 NM

VOR portion unusable:

111°-164° byd 10 NM blo 2,000'

241°-251°

TACAN unusable:

025°-035° byd 10 NM blo 3,000'

268°-274° byd 30 NM blo 5,000'

