

FORT WORTH

BOURLAND FLD (50F) 17 SW UTC-6(-5DT) N32°34.91' W97°35.45'

873 B NOTAM FILE FTW

RWY 17-35: H4049X60 (ASPH) MIRL 0.9% up N

RWY 17: VASI(V2L)—GA 3.0° TCH 23'. Thld dsplcd 392'. Road.

RWY 35: VASI(V2L)—GA 3.0° TCH 24'. Thld dsplcd 215'. Trees.

SERVICE: FUEL 100LL, JET A **LGT** ACTVT VASI Rwy 17 and Rwy 35; MIRL Rwy 17-35—CTAF.

AIRPORT REMARKS: Attended Mon-Sat dalgt hours. For svcs aft hrs call 817-752-4701. Fuel avbl self serve and full svc. Brush and trees obscure view of rwy and apch at try hold psns.

AIRPORT MANAGER: 817-752-4701

COMMUNICATIONS: CTAF/UNICOM 123.0


Ⓡ **REGIONAL APP/DEP CON** 135.975

CLEARANCE DELIVERY PHONE: For CD ctc Regional Apch at 972-615-2799.

RADIO AIDS TO NAVIGATION: NOTAM FILE FTW.

MILLSAP (H) VORTACW 117.7 MQP Chan 124 N32°43.57' W97°59.85' 104° 22.3 NM to fld. 900/9E.

DALLAS-FT WORTH
COPTER
L-17C, A
IAP



FORT WORTH ALLIANCE (AFW)(KAFW) 14 N UTC-6(-5DT) N32°59.42' W97°19.17'

723 B LRA ARFF Index—See Remarks NOTAM FILE AFW

RWY 16R-34L: H11010X150 (CONC-GRVD) D-200, 2S-175, 2D-400, 2D/2D2-870 PCN 82 R/B/W/T HIRL

RWY 16R: REIL. PAPI(P4R)—GA 3.0° TCH 75'. Railroad. Rgt tfc. 0.4% down.

RWY 34L: REIL. PAPI(P4L)—GA 3.0° TCH 74'. Thld dsplcd 601'. Fence. 0.7% up.

RWY 16L-34R: H11000X150 (CONC-GRVD) D-200, 2S-175, 2D-400, 2D/2D2-870 PCN 82 R/B/W/T HIRL CL

RWY 16L: ALSF2. TDZL. RVR-TMR Rgt tfc. 0.4% down.

RWY 34R: MALSR. RVR-TMR P-line. 0.7% up.

RUNWAY DECLARED DISTANCE INFORMATION

RWY 16L:TORA-10600 TODA-10600 ASDA-10600

LDA-10600

RWY 16R:TORA-10399 TODA-10399 ASDA-10399

LDA-10399

RWY 34L:TORA-11000 TODA-11000 ASDA-11000

LDA-10399

RWY 34R:TORA-11000 TODA-11000 ASDA-11000

LDA-11000

SERVICE: S4 FUEL 100LL, JET A1+ OX 4

AIRPORT REMARKS: Attended continuously. Class IV, ARFF Index A.

ARFF Index E available. PPR for air carrier ops with more than 30 passenger seats, call 817-890-1000 or 800-318-9268. Last 1084' Rwy 34R not available for accelerate stop and landings. Portions of Twy H movement area east of Twy A is not visible from twr. Prior arrangements required for airframe or power plant repairs for design group III and above. U.S. Customs user fee arpt. Flight Notification Service (ADCUS) available.

AIRPORT MANAGER: 817-890-1000

WEATHER DATA SOURCES: ASOS (817) 491-6188

COMMUNICATIONS: ATIS 126.925

RGNL APP/DEP CON 118.1 124.3 125.2 125.8 125.9 135.975

ALLIANCE TOWER 120.825 (Helicopters) 135.15 **CLNC DEL** 128.725 **GND CON** 132.65

AIRSPACE: CLASS D svc continuous.

RADIO AIDS TO NAVIGATION: NOTAM FILE FTW.

RANGER (H) VORTACW 115.7 FUZ Chan 104 N32°53.37' W97°10.77' 305° 9.3 NM to fld. 638/6E.

ILS/DME 110.15 I-UIPE Chan 38(Y) Rwy 16L. Class IIIE. DME also serves Rwy 34R. DME unusable 23° left of course.

ILS/DME 110.15 I-JVX Chan 38(Y) Rwy 34R. Class ID. DME also serves Rwy 16L.

COMM/NAV/WEATHER REMARKS: Emerg frequency not available. ARINC frequency 129.75 avbl.

DALLAS-FT WORTH
COPTER
H-6H, L-17C, A
IAP, AD

