

INIGOK (4AK1) PVT 96 W UTC-9(-8DT) N70°00.23' W153°04.65'

POINT BARROW

191 B NOTAM FILE FDC Not insp.

H-1A, L-4I

RWY 02-20: 5000X150 (GRVL) 0.6% up S

AIRPORT REMARKS: Unattended. Closed to the public. Bureau of Land Management (BLM) installation. All acft ops shall obtain a permit prior to intended ldg. Ctc the BLM Arctic fld Office, 1150 University Avenue, Fairbanks, AK 99709 (http://www.blm.gov/ak/st/en/fo/fdo/arctic_field_office.html) or call 907-474-2200 to apply for a permit 45 days prior to intended ldg. Failure to obtain and have onboard an apvd permit will result in trespass violations and possibly criminal and civ actions. Rwy not maintained, recommend visual inspection prior to ldg. Rwy 02 multiple soft spots last 2000'. 25' antenna 650' NW of Rwy 02.

AIRPORT MANAGER: 907-474-2200

COMMUNICATIONS: CTAF/UNICOM 122.8

COMM/NAV/WEATHER REMARKS: For a local call to Barrow FSS dial 852-2511. For a toll free call to Fairbanks FSS dial 1-866-248-6516.

DEERING (DEE)(PADE) 2 SW UTC-9(-8DT) N66°04.15' W162°46.02'

NOME

30 B NOTAM FILE DEE

L-4H

RWY 03-21: 3320X75 (GRVL) MIRL

IAP

RWY 03: REIL. PAPI(P4R)—GA 3.0° TCH 25'.

RWY 12-30: 2660X75 (GRVL) MIRL 0.4% up NW

SERVICE: LGT ACTIVATE MIRL Rwy 03-21 and Rwy 12-30; REIL Rwy 03 and PAPI Rwy 03 —CTAF. ACTIVATE rotating bcn —CTAF.

AIRPORT REMARKS: Unattended. Migratory birds as well as musk oxen and other large animals on and invof of rwys. Rwy cond not monitored, recommend visual inspection prior to ldg. Cold temperature restricted airport. Altitude correction required at or below -40C. Rwy 03-21 plowed in winter. Windssock missing at Rwy 12. Rwy 03-21 NSTD markings, marked with lgts and plastic markers. Rwy 12-30 NSTD markings, marked with lgts and plastic markers.

AIRPORT MANAGER: 907-442-3147

WEATHER DATA SOURCES: ASOS 135.5 (907) 363-2102. (WX CAM)

COMMUNICATIONS: CTAF 122.9


DEERING RCO 122.25 (KOTZEBUE RADIO)

ANCHORAGE CENTER APP/DEP CON 119.2 263.0

RADIO AIDS TO NAVIGATION: NOTAM FILE OTZ.

KOTZEBUE (H) VOR/DME 115.7 OTZ Chan 104 N66°53.14' W162°32.40' 171° 49.5 NM to fld. 121/15E.

COMM/NAV/WEATHER REMARKS: For a LC to Kotzebue FSS dial 907-442-3310. For a toll free call to Kotzebue FSS dial 1-800-478-7460. For a toll free call to Fairbanks FSS dial 1-866-248-6516.



DELTA DAVES (See DELTA JUNCTION on page 91)

DELTA JUNCTION

ALL WEST (AK77) PVT 11 E UTC-9(-8DT) N63°56.49' W145°25.33'

ANCHORAGE

1275 NOTAM FILE Not insp.

H-1B, L-1A, 3B, 3E

RWY 09-27: 5500X75 (TURF-GRVL)

AIRPORT REMARKS: Unattended.

AIRPORT MANAGER: 907-895-9800

COMM/NAV/WEATHER REMARKS: For a toll free call to Fairbanks FSS dial 1-866-248-6516.

DELTA DAVES (AA22) PVT 7 NW UTC-9(-8DT) N64°07.97' W145°48.27'

FAIRBANKS

1050 NOTAM FILE Not insp.

RWY 15-33: 2350X60 (TURF)

RWY 15: Trees.

RWY 33: Rgt tfc.

AIRPORT REMARKS: Unattended.

AIRPORT MANAGER: 907-895-4887

COMM/NAV/WEATHER REMARKS: For a toll free call to Fairbanks FSS dial 1-866-248-6516.