
DESERT AIRE RGNL (See MATTAWA on page 198)

DOROTHY SCOTT INTL (See OROVILLE on page 204)

EASTON STATE (ESW)(KESW) 2 N UTC-8(-7DT) N47°15.25' W121°11.13' SEATTLE
 2226 NOTAM FILE SEA
RWY 09-27: 2640X100 (TURF) LIRL 0.5% up W
RWY 09: Trees.
RWY 27: Trees.
AIRPORT REMARKS: Unattended. Arpt CLOSED Oct 1 thru Jun 1 exc for approved military and public safety/law enforcement helicopter ops. Ctc WA State Aviation Division 360-709-8015 or 1-800-552-0666 WA area for facility info prior to use. For acft accidents/incidents ctc WA state emergency operations center 800-258-5990. Wind cone mounted on 50' self supporting twr. Vehicles, pedestrians, or wildlife on and invof rwy. LIRL opr dusk to dawn during dates arpt is open.
AIRPORT MANAGER: (360) 618-2477
COMMUNICATIONS: CTAF 122.9
CLEARANCE DELIVERY PHONE: For CD ctc Seattle ARTCC at 253-351-3694.

EASTSOUND
ORCAS ISLAND (ORS)(KORS) 1 N UTC-8(-7DT) N48°42.50' W122°54.64' SEATTLE
 35 B TPA-1035(1000) NOTAM FILE ORS L-1E
RWY 16-34: H2901X60 (ASPH-AFSC) S-12.5 MIRL 0.8% up S IAP
RWY 16: REIL. PAPI(P4R)—GA 3.48° TCH 35'. Road.
RWY 34: REIL. PAPI(P2L)—GA 4.0° TCH 26'. Trees. Rgt tfc.
SERVICE: S4 FUEL 100LL LGT ACTVT REIL Rwy 16 and Rwy 34; PAPI Rwy 16; MIRL Rwy 16-34; twy lghts—CTAF. REIL Rwy 16 and Rwy 34 on photocell and not avbl durg dalgt. Rwy 34 PAPI unsubl byd 2 degs left of cntrin.
NOISE: NS ABTMT procedures in effect, ctc arpt manager 360-376-5285.
AIRPORT REMARKS: Attended 1600-0030Z†. Self svc 24 hr fuel avbl with credit card. Deer on and invof rwy. Preferred Rwy 16 in calm wind cond. Nighttime circling apchs not permitted from west side of rwy. Additional tran turf tiedowns south of segmented circle. Ldg on grass sfc prohibited.
AIRPORT MANAGER: 360-376-5285
WEATHER DATA SOURCES: AWOS-3 135.425 (360) 376-6045.
COMMUNICATIONS: CTAF 128.25
MT CONSTITUTION RCO 122.3 (SEATTLE RADIO)
WHIDBEY APP/DEP CON 118.2 (ARR and DEP to the South)
VICTORIA TERMINAL APP/DEP CON 132.7 (ARR and DEP to the North)
CLEARANCE DELIVERY PHONE: For CD for dep from rwy 16/34, ctc Victoria trml on 133.95 or at 604-586-4561.
RADIO AIDS TO NAVIGATION: NOTAM FILE BLI.
WHATCOM (H) VORTACW 113.0 HUH Chan 77 N48°56.72' W122°34.76' 203° 19.4 NM to fld. 82/20E.
 TACAN AZIMUTH unusable:
 155°-165° byd 15 NM blo 6,000'

EATONVILLE
SWANSON (2W3) 1 NE UTC-8(-7DT) N46°52.30' W122°15.43' SEATTLE
 843 TPA-1643(800) NOTAM FILE SEA
RWY 16-34: H2990X36 (ASPH) MIRL
RWY 16: Trees. Rgt tfc.
RWY 34: Ground.
SERVICE: LGT Arpt lghts opr dusk-0800Z†. After 0800Z†, ACTIVATE MIRL Rwy 16-34—CTAF.
AIRPORT REMARKS: Attended 1600-0400Z†. Deer on and in vicinity of arpt. Bldgs are in close proximity to rwy. Gravel svc road around Rwy 16-34 not avbl for acft ops. Taxi on rwy. Rwy 16-34 trees in apch and transitional sfc both sides of rwy. Restrooms and bicycles avbl at Trinity Aviation Academy.
AIRPORT MANAGER: (253) 888-0929
COMMUNICATIONS: CTAF 122.9
CLEARANCE DELIVERY PHONE: For CD ctc Seattle Apch at 206-214-4723.

ED CARLSON MEML FLD – SOUTH LEWIS CO (See TOLEDO on page 226)

EDIZ HOOK N48°08.39' W123°24.20' NOTAM FILE SEA. SEATTLE
NDB (MHW) 338 NOW at Port Angeles Cgas. 6/17E. L-1E
 NDB unusable:
 120°-190° byd 10 NM
 190°-120° byd 15 NM