196 WASHINGTON

LAURIER

AVEY FLD (69S) 2 SW UTC-8(-7DT) N48°59.90′ W118°13.36′

SEATTLE

1655 NOTAM FILE SEA **RWY 17–35**: 1975X40 (GRVL)

RWY 17: Trees. RWY 35: Trees.

AIRPORT REMARKS: Unattended. Vehicles and animals on and invof rwy. Rwy 17 marked with retro-reflective devices.

Helicopter operations on airport during fire season. Shoulders very soft and rough both sides of rwy. Canadian and U.S. customs avbl on hwy to the west. U.S. based acft should park on the U.S. side of ramp, south, and Canadian based acft should park on north side of ramp.

AIRPORT MANAGER: 509-684-2240
COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Seattle ARTCC at 253-351-3694.

LEAVENWORTH

LAKE WENATCHEE STATE (27W) 14 NW UTC-8(-7DT) N47°49.16′ W120°43.19′

SEATTLE

1939 NOTAM FILE SEA

RWY 09-27: 2473X100 (TURF) 0.4% up W

RWY 09: Road. RWY 27: Road.

AIRPORT REMARKS: Unattended. CLOSED 1 Oct-1 Jun. Pedestrians, vehicles and animals on and invof rwy. Two windsocks, one at each rwy end. Ctc WA State Aviation Division 360–709–8015 or 1–800–552–0666 WA area for facility info prior to use. For actt accidents/incidents ctc WA state emergency operations center 800–258–5990. Rwy marked with reflectors dur dates arot is open.

AIRPORT MANAGER: (360) 618-2477
COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Seattle ARTCC at 253-351-3694.

LESTER STATE (15S) 2 E UTC-8(-7DT) N47°12.91′ W121°27.74′

SEATTLE

1693 NOTAM FILE SEA **RWY 05–23**: 400X100 (TURF)

RWY 05: Tree. RWY 23: Tree.

AIRPORT REMARKS: Unattended. Arpt clsd to fixed wing acft indef. Rwy 05–23 clsd indef due to severe erosion from river. Vehicles, pedestrians and animals on and invof rwy. Ctc WA State Aviation Division 360–651–6300 or 1–800–552–0666

WA area for facility info prior to use. Rwy 05–23 sfc rough. Rwy sfc not maintained, very tall grass and weeds.

AIRPORT MANAGER: (360) 618-2477 Communications: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Seattle ARTCC at 253-351-3694.

.

HELIPAD H1: 100X100 (TURF)

 $\textbf{\textit{HELIPORT REMARKS}} : \textbf{Grass area available for emergency helicopter operations}.$

LIND (ØSØ) 2 NE UTC-8(-7DT) N46°58.61′ W118°35.23′

SEATTLE L-13A

1507 B NOTAM FILE SEA **RWY 05–23**: H3197X50 (ASPH) HIRL

RWY 23: Hill

SERVICE: LGT ACTIVATE HIRL Rwy 05-23-CTAF.

AIRPORT REMARKS: Unattended. East end of rwy has 800 ' by 50 ' dirt graded safety area. Rwy 05–23 markings faded.

AIRPORT MANAGER: 509-677-3241

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Grant County Apch at 509-762-2842, when Apch clsd ctc Seattle ARTCC at

253-351-3694

RADIO AIDS TO NAVIGATION: NOTAM FILE MWH.

MOSES LAKE (H) VORW/DME 115.0 MWH Chan 97 N47°12.65′ W119°19.01′ 097° 33.0 NM to fld. 1193/18E.

LITTLE GOOSE LOCK AND DAM (See STARBUCK on page 224)