

BRIDGEPORT

BRYANT FLD (O57) 0 NE UTC-8(-7DT) N38°15.88' W119°13.36'

SAN FRANCISCO

6472 B TPA-7172(700) NOTAM FILE RAL

L-9A

RWY 16-34: H3854X60 (ASPH) S-30 MIRL

RWY 16: Rgt tfc.

RWY 34: Road.

SERVICE: FUEL 100 LGTACTIVATE MIRL Rwy 16-34-122.8.

AIRPORT REMARKS: Unattended. Fuel self service. Rotating bcn located 1/4 mile E of the arpt on top of hill. Birds tend to congregate at N end of rwy. Arpt located in mountainous terrain. Hillside located 1644 ft east of AER 34 and 1815 ft east of AER 16. Vehicles on hwy parallel to rwy 180 ft east of AER 16 to midfield. Several unlit 40-80' trees are at 225-550' east of the rwy cntrln along the south two thirds of the rwy.

AIRPORT MANAGER: 760-932-5457


COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Oakland ARTCC at 510-745-3380.

RADIO AIDS TO NAVIGATION: NOTAM FILE RNO.

MINA (H) VORTAC 115.1 MVA Chan 98 N38°33.92' W118°01.97' 236° 58.9 NM to fld, 7860/17E.

VOR/DME & TACAN AZIMUTH unusable:
130°-160° byd 28 NM blo 10,700'



BROWN FLD MUNI (See SAN DIEGO on page 212)

BRYANT FLD (See BRIDGEPORT on page 99)

BUCHANAN FLD (See CONCORD on page 115)