





LOC/DME I-DDV 110.1 Chan 38	APP CRS 052°	Rwy Idg 12102 TDZE 736 Apt Elev 744
---	------------------------	--

ILS RWY 5R (SA CAT I)


RICKENBACKER INTL (LCK)

ADF or DME required.	ALSF-2	MISSED APPROACH: Climb to 1500 then climbing right turn to 3000 direct XUB VOR and hold.
Requires specific OPSPEC, MSPEC or LOA approval.		

ATIS 132.75	COLUMBUS APP CON 134.0 279.6	RICK TOWER 120.05 348.4	GND CON 125.275 275.8	CLNC DEL 125.275 275.8
-----------------------	--	-----------------------------------	---------------------------------	----------------------------------



ELEV 744	D	TDZE 736
----------	---	----------



CATEGORY	A	B	C	D
S-ILS 5R	RA 150/14 150 DA 886			

SA CATEGORY I ILS - SPECIAL AIRCREW & AIRCRAFT CERTIFICATION REQUIRED

TDZ/CL Rwy 5R
REIL Rwy 23R
HIRL Rwys 5L-23R and 5R-23L

EC-2, 07 OCT 2021 to 04 NOV 2021

EC-2, 07 OCT 2021 to 04 NOV 2021