

HARBOR SPRINGS (MGN)(KMGN) 3 E UTC-5(-4DT) N45°25.53' W84°54.81'

LAKE HURON

686 B NOTAM FILE MGN

L-31B

RWY 10-28: H4149X75 (ASPH) S-22, D-30 MIRL


IAP

RWY 10: PAPI(P4R)—GA 3.5° TCH 28'. Thld dsplcd 437'. Pole.**RWY 28:** PAPI(P4L)—GA 4.0° TCH 35'. Thld dsplcd 444'. Trees.**SERVICE:** FUEL 100LL, JET A LGT ACTIVATE MIRL Rwy 10-28, PAPI Rwy 10 and Rwy 28—CTAF. Rwy 28 PAPI NSTD. Rwy 28 PAPI unusable byd 2° left of centerline.**NOISE:** Noise abatement procedures; no turbojet/turbofan acft depts fm 0400-1200Z±, no low flight ovr surrounding community, all acft depg to the W turn S ovr the water as soon as practical.**AIRPORT REMARKS:** Attended 1300-dusk. Parachute Jumping. Birds and deer on and infov arpt. Rwy 28 +46' antenna 186' from dsplcd thld 234' right. Rwy 10 has 2 lgtd obstruction poles 189' left, +70' trees on N side. Rwy 28 has lgtd obstruction poles each side of rwy. 80' trees in side slope lgtd. Landing fee waived with minimum fuel purchase.**AIRPORT MANAGER:** 231-347-2812**WEATHER DATA SOURCES:** AWOS-3 119.925 (231) 347-5231. Wind unreliable btm 260 & 280 degs.**COMMUNICATIONS:** CTAF/UNICOM 122.8® **MINNEAPOLIS CENTER APP/DEP CON** 134.6**CLEARANCE DELIVERY PHONE:** For CD ctc Minneapolis ARTCC at 651-463-5588.**RADIO AIDS TO NAVIGATION:** NOTAM FILE PLN.**PELLSTON (L) (L) VORTACW** 111.8 PLN Chan 55 N45°37.84' W84°39.85' 227° 16.2 NM to fld. 835/6W.

VOR unusable:

301°-339°

GCP has azm only, no DME at GCP

**HARRIETTA****EAGLES LANDING** (4Y9) 3 W UTC-5(-4DT) N44°18.46' W85°46.32'

GREEN BAY

993 NOTAM FILE LAN

RWY 08-26: 2400X100 (TURF) 0.8% up E**RWY 08:** Trees.**RWY 26:** Trees.**AIRPORT REMARKS:** Unattended. Arpt CLOSED when snow covered. Rwy 08-26 sfc rough and uneven. Large depression east of Rwy 26 end. Rwy 08-26 marked with 3' yellow cones. 60' trees both sides of rwy 100' from rwy centerline.**AIRPORT MANAGER:** (586) 944-7101**COMMUNICATIONS:** CTAF 122.9**CLEARANCE DELIVERY PHONE:** For CD ctc Minneapolis ARTCC at 651-463-5588.**HARRISON****CLARE CO** (8ØD) 2 NW UTC-5(-4DT) N44°03.14' W84°48.79'

LAKE HURON

1142 B NOTAM FILE LAN

RWY 05-23: 3000X100 (TURF)**RWY 05:** Trees.**RWY 23:** Thld dsplcd 800'. Bldg.**RWY 18-36:** H2978X50 (ASPH) LIRL(NSTD)**RWY 18:** Thld dsplcd 465'. Trees.**RWY 36:** Thld dsplcd 1160'. Trees.**RWY 09-27:** 2403X100 (TURF)**RWY 09:** Thld dsplcd 1196'. Trees.**RWY 27:** Thld dsplcd 837'. Road.**SERVICE:** LGT ACTIVATE NSTD LIRL—CTAF. Rwy 18-36 NSTD LIRL due to improper color and lctn.**AIRPORT REMARKS:** Unattended. Deer on and infov arpt. Rwy 09-27 and Rwy 05-23 CLOSED Nov-Mar and when snow covd exc for ski equipped acft. Rwy 27, 22' p-line, 308' distance, apch ratio 14:1, mkd with orange balls. Rwy 18-36 extsv cracking. Rwy 09-27 and dthr mkd with 3' yellow cones. Rwy 09-27 inter patches of misg turf thrut full len and wid. Rwy 05-23 and dthr mkd with 3' yellow cones. Rwy 5 dthr extds byd rwy midpt. Rwy 05-23 inter patches of misg turf thrut full len and wid.**AIRPORT MANAGER:** 989-862-5333**COMMUNICATIONS:** CTAF/UNICOM 122.8**CLEARANCE DELIVERY PHONE:** For CD ctc Minneapolis ARTCC at 651-463-5588.