

LAKEVIEW

LAKE CO (LKV)(KLKV) 3 SW UTC-8(-7DT) N42°09.67' W120°23.95'

KLAMATH FALLS
H-3B, L-11A
IAF

4734 B NOTAM FILE LKV

RWY 17-35: H5318X100 (ASPH) S-74, D-86 MIRL

RWY 17: REIL. PAPI(P4R)—GA 3.0° TCH 45'.

RWY 35: REIL. PAPI(P4L)—GA 3.0° TCH 45'.

SERVICE: S4 **FUEL** 100LL, **JET A** **LGT** ACTIVATE MIRL Rwy 17-35; PAPI Rwy 17 and Rwy 35; REIL Rwy 17 and Rwy 35—CTAF.

Tetrahedron lighting inop. Rwy 17 thld lgts, Rwy 17-35 edge lgts and Twy B edge reflectors obscured by vegetation.

AIRPORT REMARKS: Attended Apr-Sep 1700-0000Z†, Oct-Mar 1500-0100Z†. Flocks of large waterfowl in vcnty Nov-May. Wildlife on and infov arpt. Extv airtanker ops in fire season. Possible glider ops on twy. Drag strip oriented NW-SE lctd 3000' southwest of Rwy 35. Twy NE-SW used for strong cross wind ldg.

AIRPORT MANAGER: 541-947-4222

WEATHER DATA SOURCES: AWOS-3PT 135.525 (541) 947-5069.

COMMUNICATIONS: CTAF/UNICOM 122.8


RCO 122.3 (MC MINNVILLE RADIO)

Ⓡ SEATTLE CENTER APP/DEP CON 127.6

CLEARANCE DELIVERY PHONE: For CD if una to ctc on FSS freq, ctc Seattle ARTCC at 253-351-3694.

RADIO AIDS TO NAVIGATION: NOTAM FILE LKV.

LAKEVIEW (H) (H) VORTACW 112.0 LKV Chan 57 N42°29.57' W120°30.43' 147° 20.5 NM to fld. 7465/19E.



LEBANON STATE (S3Ø) 1 SW UTC-8(-7DT) N44°31.87' W122°55.78'

SEATTLE

349 B NOTAM FILE MMV

RWY 16-34: H2747X60 (ASPH) MIRL

RWY 16: PAPI(P2L)—GA 3.5° TCH 40'. Tree.

RWY 34: PAPI(P2L)—GA 3.0° TCH 44'. Thld dspcd 260'. Road.

SERVICE: S4 **FUEL** 100LL, **MOGAS** **LGT** ACTVT PAPI RWY 16 & 34; MIRL RWY 16-34—CTAF.

AIRPORT REMARKS: Attended continuously. Acft departing Rwy 34 make 10° left turn after tkl as soon as safety permits.

AIRPORT MANAGER: 503-378-4880

COMMUNICATIONS: CTAF/UNICOM 122.8

CLEARANCE DELIVERY PHONE: For CD ctc Cascade Apch at 541-607-4674/4675, when Apch clsd ctc Seattle ARTCC at 253-351-3694.

LENHARDT AIRPARK (See HUBBARD on page 148)

LEWISBURG N44°36.82' W123°16.24' NOTAM FILE CVO.

KLAMATH FALLS
L-11B

NDB (MHV) 225 LWG 172° 7.0 NM to Corvallis Muni. 330/15E.

LEXINGTON (9S9) 1 N UTC-8(-7DT) N45°27.25' W119°41.42'

SEATTLE
L-13A
IAF

1635 B NOTAM FILE MMV

RWY 08-26: H4156X75 (ASPH) S-12.5 MIRL 1.3% up E

RWY 08: PAPI(P2L)—GA 3.0° TCH 43'. Fence.

RWY 26: PAPI(P2L)—GA 3.5° TCH 47'.

SERVICE: **FUEL** 100LL **LGT** ACTIVATE MIRL Rwy 08-26 and PAPI Rwy 08 and Rwy 26—CTAF.

AIRPORT REMARKS: Unattended. Fuel 24 hours credit card svc.avbl. Wildlife on and infov arpt. Rwy 08-26 200' gravel east end.

AIRPORT MANAGER: 541-989-9500

WEATHER DATA SOURCES: AWOS-3 134.475 (541) 989-8557.

COMMUNICATIONS: CTAF 122.9

Ⓡ SEATTLE CENTER APP/DEP CON 132.6

CLEARANCE DELIVERY PHONE: For CD ctc Seattle ARTCC at 253-351-3694.

RADIO AIDS TO NAVIGATION: NOTAM FILE PDT.

PENDLETON (H) (H) VORTACW 114.7 PDT Chan 94 N45°41.91' W118°56.32' 231° 34.9 NM to fld. 1575/14E.

