

**VIVIAN** (3F4) 2 SW UTC-6(-5DT) N32°51.68' W94°00.61'

260 B NOTAM FILE DRI

**RWY 09-27:** H2998X75 (ASPH) S-12 MIRL 0.4% up E

**RWY 09:** REIL. PAPI(P2L)—GA 3.0° TCH 52'. Trees.

**RWY 27:** REIL. Trees.

**SERVICE:** S4 **FUEL** 100LL **LGT** MIRL Rwy 09-27 and REIL Rwy 09 preset low instst dusk-dawn; to incr instst actvt—CTAF. Rwy 09 PAPI out of service.

**AIRPORT REMARKS:** Attended Mon-Sat dawn-dusk. Fuel avbl 24 hrs self svc with credit card. Parachute activity invof arpt.

**AIRPORT MANAGER:** (318) 455-5499

**COMMUNICATIONS:** CTAF/UNICOM 122.8

® **SHREVEPORT APP/DEP CON** 119.9

**GCO** 135.075 (BARKSDALE APCH CTL and FLIGHT SERVICES)

**CLEARANCE DELIVERY PHONE:** For CD if una via GCO ctc Fort Worth ARTCC at 817-858-7584.

**RADIO AIDS TO NAVIGATION:** NOTAM FILE SHV.


**BELCHER (H) (H) VORTACW** 117.4 EIC Chan 121 N32°46.28'

W93°48.60' 291° 11.5 NM to fld. 190/7E.

**MEMPHIS**

L-13D, 17E

IAP



**WELSH** (6R1) 0 NW UTC-6(-5DT) N30°14.51' W92°49.84'

18 B NOTAM FILE DRI

**RWY 07-25:** H2700X50 (ASPH) S-6 MIRL

**RWY 07:** Trees.

**RWY 25:** Trees.

**RWY 09-27:** 2200X150 (TURF)

**RWY 09:** Trees.

**RWY 27:** Trees.

**AIRPORT REMARKS:** Attended irregularly. Rwy 07-25 has some sml longl cracks with grass growth. Block cracks with grass growth Rwy 07 tarnd.

**AIRPORT MANAGER:** 337-570-5490

**COMMUNICATIONS:** CTAF/UNICOM 122.8

® **LAKE CHARLES APP/DEP CON** 119.8 (1200-0400Z‡)

® **HOUSTON CENTER APP/DEP CON** 124.7 (0400-1200Z‡)

**CLEARANCE DELIVERY PHONE:** For CD ctc Lake Charles Apch at 337-480-3103, when Apch clsd ctc Houston ARTCC at 281-230-5622.

**RADIO AIDS TO NAVIGATION:** NOTAM FILE LCH.

**LAKE CHARLES (H) (H) VORTACW** 113.4 LCH Chan 81 N30°08.49' W93°06.33' 060° 15.5 NM to fld. 20/7E.

VOR portion unusable:

Byd 30 NM blo 1,500'

**HOUSTON**

L-21B, 22E, GOMW

IAP

**WHITE LAKE** N29°39.79' W92°22.42' NOTAM FILE DRI.

(L) **VORW/DME** 110.4 LLA Chan 41 5/4E.

**HOUSTON**

H-7D, L-21B, 22E, GOMC, GOMW