

BEAUFORT**MICHAEL J SMITH FLD** (MRH)(KMRH) 1 N UTC-5(-4DT) N34°44.03' W76°39.62'CHARLOTTE
H-9C, L-35B
IAF

10 B TPA—See Remarks LRA NOTAM FILE MRH

RWY 08-26: H5004X100 (ASPH) D-60 MIRL**RWY 08:** REIL. PAPI(P2L)—GA 3.0° TCH 45'. Brush.**RWY 26:** REIL. PAPI(P2R)—GA 3.0° TCH 43'. Thld dspcld 289'. Road. Rgt tfc.**RWY 03-21:** H4192X150 (ASPH) S-12.5 MIRL**RWY 03:** PAPI(P2L)—GA 4.0° TCH 44'. Thld dspcld 864'. Road.**RWY 21:** PAPI(P2L)—GA 4.0° TCH 54'. Thld dspcld 516'. Trees. Rgt tfc.**RWY 14-32:** H4001X100 (ASPH) S-12.5**RWY 14:** Brush.**RWY 32:** Thld dspcld 490'. Trees.**SERVICE:** S4 **FUEL** 100LL, JET A1+ **OX** 3, 4 **LGT** ACTIVATE REIL Rwy 08 and Rwy 26; PAPI Rwy 03 and Rwy 21; MIRL Rwy 03-21 and Rwy 08-26—CTAF. PAPI Rwy 08 and Rwy 26 opr continuously.**NOISE:** Noise abatement procedures in effect, ctc amgr 252-728-1928. Mil acft Rwy 08-26 required for noise abatement. Avoid overflights of Beaufort Waterfront and Beaufort National Register Historic District.**AIRPORT REMARKS:** Attended 1300Z±-dusk. For service after hours call 843-465-2846. Deer and birds on and invof arpt and bird-dropped shells may cause FOD. Skydiving operations - do not overfly arpt. TPA—single engine 1000 ft AGL, twin engine 1500 ft AGL. No line of sight btwn rwy ends.**AIRPORT MANAGER:** 252-728-1928**WEATHER DATA SOURCES:** ASOS 135.375 (252) 728-2055.**COMMUNICATIONS:** CTAF/UNICOM 122.8Ⓡ **CHERRY POINT APP/DEP CON** 132.575

CLNC DEL 125.65


CLEARANCE DELIVERY PHONE: For CD ctc Cherry Point Apch at 252-466-5960.**RADIO AIDS TO NAVIGATION:** NOTAM FILE ISO.**KINSTON (L) (L) VORTAC** 109.6 ISO Chan 33 N35°22.26' W77°33.50' 136° 58.4 NM to fld. 70/5W.

VOR unusable:

221°-231° byd 30 NM blo 2,000'

Blo 5,000'

Byd 10NM

COMM/NAV/WEATHER REMARKS: Due to volume of mil tfc and trng rcmd all acft using MRH ctc Cherry Point App 132.57 AB and 125.65 prior to MRH dep.**BILLY MITCHELL** (See HATTERAS on page 302)**BLADENBORO** (3W6) 0 E UTC-5(-4DT) N34°32.57' W78°46.69'

CHARLOTTE

116 NOTAM FILE RDU

RWY 02-20: 2850X135 (TURF) 0.6% up N**RWY 02:** Trees.**RWY 20:** Trees.**AIRPORT REMARKS:** Unattended. Rwy 20 has 90' trees 100' from thld offset 30' rgt of cntrln and 90' trees 250' from thld offset 100' left of cntrln. 80' trees west edge of rwy thld to thld and 80' trees east edge of Rwy 02 from thld to 500'.**AIRPORT MANAGER:** (910) 876-4225**COMMUNICATIONS:** CTAF 122.9**CLEARANCE DELIVERY PHONE:** For CD ctc Washington ARTCC at 703-771-3587.