

LANCASTER

KIRK AIR BASE (T73) 5 SE UTC-5(-4DT) N34°40.46' W80°40.94'

CHARLOTTE

578 NOTAM FILE AND

RWY 15-33: H2600X40 (ASPH) S-8 LIRL

RWY 33: Tree.

SERVICE: S4 FUEL 100LL LGT For LIRL Rwy 15-33 call 803-286-8800.

AIRPORT REMARKS: Attended 1300-2330Z±. Rwy 15 has 30' drop at thld. Rwy 33 has 10' drop at thld.

AIRPORT MANAGER: 803-286-8800

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Charlotte Apch at 704-359-0241.

WATERWAY 05W-23W: 4400X300 (WATER)

WATERWAY 16W-34W: 3000X300 (WATER)

WATERWAY 11W-29W: 2245X600 (WATER)

SEAPLANE REMARKS: Waterways 05-23, 11-29 and 16-34 water lanes are not marked, lengths change with water levels ctc arpt mgr and check NOTAM's.

LANCASTER CO-MC WHIRTER FLD (LKR)(KLKR) 4 W UTC-5(-4DT) N34°43.37'

CHARLOTTE

W80°51.28'

H-9B, 12G, L-24J, 25D, 36E
IAP

486 B NOTAM FILE AND

RWY 06-24: H6004X101 (CONC) S-44, D-60, 2D-118

PCN 15 R/B/X/T MIRL 0.4% up NE

RWY 06: REIL. PAPI(P2L)-GA 3.0° TCH 41'. Thld displcd 105'. Tree.

RWY 24: REIL. PAPI(P2L)-GA 3.15° TCH 39'. Tree.

SERVICE: FUEL 100LL, JET A LGT Actvt REIL Rwy 06 & 24; MIRL Rwy 06-24-CTAF.

AIRPORT REMARKS: Attended 1230-2000Z±. Deer on and invof arpt. For fuel after hrs call 803-285-1513. Small acct must be on a tie down. Arl applicators not prmtd due to pavement conds.

AIRPORT MANAGER: (803) 285-1513

WEATHER DATA SOURCES: AWOS-3 120.825 (803) 286-6444.

COMMUNICATIONS: CTAF/UNICOM 122.725

Ⓡ CHARLOTTE APP/DEP CON 120.05

GCO 121.725 (CHARLOTTE APCH)

CLEARANCE DELIVERY PHONE: For CD ctc Charlotte Apch at 704-359-0241.

RADIO AIDS TO NAVIGATION: NOTAM FILE CLT.

CHARLOTTE (L) (L) VOR/DME 115.0 CLT Chan 97 N35°11.42'

W80°57.11' 175° 28.4 NM to fld. 732/5W.

DME portion unusable:

015°-050° byd 25 NM blo 3,000'

050°-100° byd 25 NM blo 2,500'

203°-220°


270°-350° byd 20 NM blo 5,000'

VORDME controlled by charlotte ATCT

VOR unusable:

203°-220°

NDB (MHW) 400 LKR N34°43.36' W80°51.55' at fld. 481/7W. NOTAM FILE AND.



LANDRUM

FAIRVIEW (33A) 3 SE UTC-5(-4DT) N35°09.44' W82°07.43'

ATLANTA

1046 NOTAM FILE AND

RWY 14-32: H2770X30 (ASPH) S-6.5 LIRL 0.4% up NW

RWY 14: Tree. Rgt tfc.

RWY 32: Pole.

SERVICE: LGT ACTIVATE LIRL Rwy 14-32-CTAF.

AIRPORT REMARKS: Unattended. Twy markings are of wrong color. Rwy 14-32 is very bumpy with excessive patches along entire sfc length. Rwy 14-32 rwy pavement has failed in several spots. Caution should be used to land at this airfield.

AIRPORT MANAGER: 864-879-0123

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Greer Apch at 864-877-8275. when Greer Apch clsd, for CD ctc Atlanta ARTCC at 770-210-7692.