

FORTUNA N40°40.28' W124°14.07' NOTAM FILE FOT.
(L) (L) VORTACW 114.0 FOT Chan 87 016° 9.7 NM to Murray Fld. 391/19E.

KLAMATH FALLS
 H-3A, L-2H

VOR unusable:

060°-070° byd 35 NM blo 9,500'
 150°-165° byd 25 NM blo 6,500'
 165°-200° byd 25 NM blo 8,000'
 280°-330° byd 20 NM blo 3,000'
 330°-336° byd 20 NM

TACAN AZIMUTH unusable:

060°-070° byd 35 NM blo 9,500'
 150°-165° byd 25 NM blo 5,500'
 165°-200° byd 25 NM blo 8,000'
 315°-325° byd 15 NM blo 5,500'

DME unusable:

060°-070° byd 35 NM blo 9,500'
 150°-165° byd 25 NM blo 5,500'
 165°-200° byd 25 NM blo 8,000'
 315°-325° byd 15 NM blo 5,500'

FRANKLIN FLD (F72) 4 SE UTC-8(-7DT) N38°18.24' W121°25.76'
 23 NOTAM FILE RIU

SAN FRANCISCO
 L-2F, 3A

RWY 18-36: H3123X60 (ASPH) S-30

RWY 36: Rgt tfc.

RWY 09-27: H3031X60 (ASPH) S-30

RWY 09: Rgt tfc.

AIRPORT REMARKS: Unattended. Ultralights activity invof arpt. Monitor 122.9 within 5 miles. Extensive student training in area. Conduct helicopter training N of Rwy 09 and W of Rwy 36. Avoid overflight of detention facility on E side of arpt except in emerg. Calm wind Rwy 18. All rwys limited to 12,500 lbs gross weight.

AIRPORT MANAGER: 916-875-9035

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD etc NorCal Apch at 916-361-6874.

RADIO AIDS TO NAVIGATION: NOTAM FILE SAC.

SACRAMENTO (H) (H) VORTACW 115.2 SAC Chan 99 N38°26.62' W121°33.10' 128° 10.2 NM to fld. 3/17E.

FRAZIER LAKE AIRPARK (See HOLLISTER on page 147)

FRENCH VALLEY (See MURRIETA/TEMECULA on page 177)