

POWERS (6S6) 1 SE UTC-8(-7DT) N42°52.16' W124°03.54'

KLAMATH FALLS

326 NOTAM FILE MMV

RWY 13-31: 2500X60 (TURF)

RWY 13: Trees.

RWY 31: Trees.

AIRPORT REMARKS: Unattended. Arpt in valley surrounded by high terrain. Livestock and wildlife on and in/ovf arpt. Rwy 31 NSTD markings, thld marked with white tires. Rwy 13 rwy end not marked. Rwy 31 has 25 ft trees w/ 35 ft of cntrn lg edge to 1700 ft m thr.

AIRPORT MANAGER: (541) 522-2737

COMMUNICATIONS: CTAF 172.9

CLEARANCE DELIVERY PHONE: For CD ctc Seattle ARTCC at 253-351-3694.

PRINEVILLE (S39) 3 SW UTC-8(-7DT) N44°17.27' W120°54.33'

KLAMATH FALLS

3251 B NOTAM FILE MMV

RWY 11-29: H5405X75 (ASPH) S-30 MIRL

RWY 29: PAPI(P4L)—GA 3.0° TCH 42'.

RWY 15-33: H4053X40 (ASPH) S-5 LIRL 0.3% up SE

SERVICE: S4 FUEL 100LL, JET A LGT ACTVT MIRL Rwy 11-29; PAPI Rwy 29 and LIRL Rwy 15-33—CTAF.

AIRPORT REMARKS: Attended Mon-Fri 1600-0030Z, Sat-Sun 1700-2200Z. 24 hr card lock self-svc fuel avbl. Deer on and in/ovf arpt. Rwy 15-33 limited by arpt opr to 5000 lbs max weight. Rwy 15-33, numerous areas of unsealed longitudinal and transverse cracking throughout full length.

AIRPORT MANAGER: 541-416-0805

WEATHER DATA SOURCES: AWOS-3PT 118.325 (541) 447-4060.

COMMUNICATIONS: CTAF/UNICOM 122.7


Ⓡ SEATTLE CENTER APP/DEP CON 126.15

CLEARANCE DELIVERY PHONE: For CD ctc Seattle ARTCC at 253-351-3694.

RADIO AIDS TO NAVIGATION: NOTAM FILE RDM.

DESCHUTES (H) (H) VORTACW 117.6 DSD Chan 123 N44°15.17' W121°18.21' 065° 17.3 NM to fld. 4103/18E.

VORTAC unusable:
220°-240° byd 30 NM



**H-18, L-13A
IAP**

PROSPECT STATE (64S) 1 S UTC-8(-7DT) N42°44.56' W122°29.34'

KLAMATH FALLS

2578 B NOTAM FILE MMV

RWY 02-20: H4000X50 (ASPH) LIRL 1.3% up N

RWY 02: Trees.

RWY 20: Trees.

SERVICE: LGT LIRL OTS indef. Trees obscure view of rotating bcn from southeast-southwest quadrants of arpt.

AIRPORT REMARKS: Unattended. Arpt clsd SS-SR. Surface conditions not reported. Irregular winter maintenance, arpt may be clsd by snow. 80'-100' trees within 200' of rwy centerline both sides of rwy. Rwy 02-20 numerous areas of unsealed longitudinal and transverse cracking throughout full length of rwy. Gaps 1/2 to 3 inch wide. Depth to 2 inch. Turf tie down area rough. Segmented circle: NSTD circle markings; tires painted white and orange.

AIRPORT MANAGER: 503-378-4880

COMMUNICATIONS: CTAF/UNICOM 122.8


CLEARANCE DELIVERY PHONE: For CD ctc Seattle ARTCC at 253-351-3694.

RADIO AIDS TO NAVIGATION: NOTAM FILE MFR.

ROGUE VALLEY (H) (H) VORTACW 113.6 OED Chan 83 N42°28.77' W122°54.78' 031° 24.5 NM to fld. 2083/19E.

TACAN AZIMUTH unusable:
245°-350° byd 30 NM blo 10,000'

VOR unusable:
260°-270° byd 35 NM blo 9,000'
290°-300° byd 35 NM blo 8,500'



L-21