


TRYBE FOUR ARRIVAL (RNAV)

CLEVELAND, OHIO



NOTE: RADAR required.

NOTE: RNAV 1.

NOTE: DME/DME/IRU or GPS required.

NOTE: Jet aircraft expect "descend via"

clearance from Cleveland Center.

NOTE: Jet aircraft descend via MACH number

until intercepting 280K. Maintain 280K

until slowed by the STAR

NOTE: CLE LANDING SOUTH: Use Rwy 24R transition,

expect runway assignment from Cleveland

APP CON no later than TRYBE.

NOTE: CLE LANDING NORTH: Use Rwy 6L transition,

expect runway assignment from Cleveland

APP CON no later than TRYBE:

NOTE: LFION transition: Except for flights originating

in Canada, do not file, to be assigned by AIC.

(NARRATIVE ON FOLLOWING PAGE)

NOTE: Chart not to scale.

TRYBE FOUR ARRIVAL (RNAV)

(TRYBE.TRYBE4) 26MAR20

CLEVELAND, OHIO