ARRIVAL ROUTE DESCRIPTION

<u>CRIBB TRANSITION (CRIBB.ROZZE2)</u> <u>MUCOW TRANSITION (MUCOW.ROZZE2)</u> <u>PONCT TRANSITION (PONCT.ROZZE2)</u> <u>QUINZ TRANSITION (QUINZ.ROZZE2)</u> <u>SMYTH TRANSITION (SMYTH.ROZZE2)</u>

Landing Rwy 6: From ROZZE on track 102° to cross PNARD between 7000 and 9000 and at 230K, then on track 111° to cross TEETO at 5000 and at 210K. Expect ILS or LOC Rwy 6 or radar vectors to final approach course.

Landing Rwy 17: From ROZZE on track 102° to cross NUUKM between 7000 and 9000, then on track 070° to cross PURBL at 5000 and at 210K. Expect RNP approach or ILS or LOC/DME Rwy 17 or radar vectors to final approach course.

Landing Rwy 24: From ROZZE on track 102° to cross NUUKM between 7000 and 9000, then on track 075° to cross JSTNN at 5000 and at 210K, then on heading 057°. Expect radar vectors to final approach course.

Landing Rwy 35: From ROZZE on track 102° to cross NUUKM between 7000 and 9000, then on track 111° to cross SHOWZ at 5000 and at 210K. Expect RNP approach or ILS or LOC Rwy 35 or radar vectors to final approach course.