

DEPARTURE ROUTE DESCRIPTION

<u>TAKEOFF RUNWAY 16:</u> Climb on heading 162° to 2500 before turning left or as assigned by ATC, thence

TAKEOFF RUNWAY 34: Climb on heading 342° to 1400 before turning southeast bound or as assigned by ATC, thence

. . . . expect RADAR vectors to cross CUZNO at or above 3000, then on track 356° to cross NANDR at or below 13000, then on assigned transition.

MC ALESTER TRANSITION (NANDR1.MLC)
OKMULGEE TRANSITION (NANDR1.OKM)
ROLLS TRANSITION (NANDR1.ROLLS)
TULSA TRANSITION (NANDR1.TUL)
WILL ROGERS TRANSITION (NANDR1.IRW)