

LAURIER

AVEY FLD (69S) 2 SW UTC-8(-7DT) N48°59.90' W118°13.36' SEATTLE
 1655 NOTAM FILE SEA
RWY 17-35: 1975X40 (GRVL)
RWY 17: Trees.
RWY 35: Trees.
AIRPORT REMARKS: Unattended. Vehicles and animals on and invof rwy. Rwy 17 marked with retro-reflective devices. Helicopter operations on airport during fire season. Shoulders very soft and rough both sides of rwy. Canadian and U.S. customs avbl on hwy to the west. U.S. based acft should park on the U.S. side of ramp, south, and Canadian based acft should park on north side of ramp.
AIRPORT MANAGER: 509-684-2240
COMMUNICATIONS: CTAF 122.9
CLEARANCE DELIVERY PHONE: For CD ctc Seattle ARTCC at 253-351-3694.

LEAVENWORTH

LAKE WENATCHEE STATE (27W) 14 NW UTC-8(-7DT) N47°49.16' W120°43.19' SEATTLE
 1939 NOTAM FILE SEA
RWY 09-27: 2473X100 (TURF) 0.4% up W
RWY 09: Road.
RWY 27: Road.
AIRPORT REMARKS: Unattended. CLOSED 1 Oct-1 Jun. Pedestrians, vehicles and animals on and invof rwy. Two windsocks, one at each rwy end. Ctc WA State Aviation Division 360-709-8015 or 1-800-552-0666 WA area for facility info prior to use. For acft accidents/incidents ctc WA state emergency operations center 800-258-5990. Rwy marked with reflectors dur dates arpt is open.
AIRPORT MANAGER: (360) 618-2477
COMMUNICATIONS: CTAF 122.9
CLEARANCE DELIVERY PHONE: For CD ctc Seattle ARTCC at 253-351-3694.

LIND (ØSØ) 2 NE UTC-8(-7DT) N46°58.61' W118°35.23' SEATTLE
 1507 B NOTAM FILE SEA L-13A
RWY 05-23: H3197X50 (ASPH) HIRL
RWY 23: Hill.
SERVICE: LGT ACTIVATE HIRL Rwy 05-23-CTAF.
AIRPORT REMARKS: Unattended. East end of rwy has 800' by 50' dirt graded safety area. Rwy 05-23 markings faded.
AIRPORT MANAGER: 509-677-3241
COMMUNICATIONS: CTAF 122.9
CLEARANCE DELIVERY PHONE: For CD ctc Grant County Apch at 509-762-2842, when Apch clsd ctc Seattle ARTCC at 253-351-3694.
RADIO AIDS TO NAVIGATION: NOTAM FILE MWH.
MOSES LAKE (H) (H) VORW/DME 115.0 MWH Chan 97 N47°12.65' W119°19.01' 097° 33.0 NM to fld.
 1193/18E.

LITTLE GOOSE LOCK AND DAM (See STARBUCK on page 237)

LOPEZ

FISHERMANS BAY SPB (81W) 1 N UTC-8(-7DT) N48°30.99' W122°55.08' SEATTLE
 00 NOTAM FILE SEA
WATERWAY 05W-23W: 3000X150 (WATER)
WATERWAY 05W: Rgt tfc.
SEAPLANE REMARKS: Unattended. Avoid overflights of houses on surrounding land. No step taxi in bay. Beware of boats anchored in seaplane ldg area.
AIRPORT MANAGER: 360-468-4116
COMMUNICATIONS: CTAF 122.9
CLEARANCE DELIVERY PHONE: For CD ctc Whidbey Apch at 360-257-3310.

LOPEZ ISLAND (S31) 3 N UTC-8(-7DT) N48°29.04' W122°56.26' SEATTLE
 209 B NOTAM FILE SEA
RWY 16-34: H2905X61 (ASPH-GRVD) S-12.5 MRL 1.6% up N
RWY 16: REIL. PAPI(P2L)—GA 4.0° TCH 43'. Trees. Rgt tfc.
RWY 34: REIL. PAPI(P2L)—GA 4.0° TCH 33'. Trees.
AIRPORT REMARKS: Unattended. Rwy 16-34 soft shoulders and thlds.
AIRPORT MANAGER: 360-468-4116
COMMUNICATIONS: CTAF 128.25
CLEARANCE DELIVERY PHONE: For CD ctc Whidbey Apch at 360-257-3310.