

NILES

JERRY TYLER MEML (3TR) 2 NE UTC-5(-4DT) N41°50.15' W86°13.51'

CHICAGO

750 B NOTAM FILE LAN

L-281

RWY 15-33: H4100X75 (ASPH) S-25 MIRL

IAP

RWY 15: REIL. PAPI(P4L)—GA 4.0° TCH 35'. Thld dspcd 300'. Trees.

RWY 33: REIL. PAPI(P4L)—GA 4.0° TCH 37'. Trees.

RWY 04-22: H3316X55 (ASPH) S-8

RWY 04: Thld dspcd 898'. Trees.

RWY 22: Thld dspcd 750'. Trees.

SERVICE: FUEL 10OLL, JET A+ LGT ACTIVATE REIL Rwy 15 and Rwy 33, PAPI Rwy 15 and Rwy 33, MIRL Rwy 15-33—CTAF. Rwy 15 PAPI unusable byd 5° right and left of centerline. Rwy 33 PAPI unusable byd 3° right and left of centerline.

AIRPORT REMARKS: Unattended. Rwy 04-22 pavement cracked and broken. Rwy 15-33 nmrs crack in pavement. Rwy 15 trsn zone +51' obstr lgtd poles. Trees between Rwy 04 and Rwy 33 and between Rwy 33 and Rwy 22 obstruct view of rwy ends.

AIRPORT MANAGER: 269-683-4700

COMMUNICATIONS: CTAF/UNICOM 122.8

Ⓡ **SOUTH BEND APP/DEP CON** 118.55 (1030-0500Z† Sun-Fri, 1030-0445Z† Sat. other times ctc)

Ⓡ **CHICAGO CENTER APP/DEP CON** 127.55

GCO 121.725 (South Bend CD and Flt Svcs)

CLEARANCE DELIVERY PHONE: For CD if una via GCO ctc south bend Apch at 574-251-2609. When south bend Apch clsd, for CD ctc Chicago ARTCC at 630-906-8921.

RADIO AIDS TO NAVIGATION: NOTAM FILE LAN.

GIPPER (H) VORTACW 115.4 GIJ Chan 101 N41°46.12' W86°19.11' 046° 5.8 NM to fld. 804/OE.

VOR portion unusable.


199°-219° blo 17,500' btn 25 and 36 NM

TACAN AZIMUTH unusable:

Byd 35 NM blo 3,500'

DME unusable:

Byd 35 NM blo 3,500'



NORTH FOX ISLAND (6Y3) 1 NE UTC-5(-4DT) N45°28.93' W85°46.85'

GREEN BAY

639 NOTAM FILE LAN

RWY 07-25: 3001X100 (TURF)

RWY 07: Thld dspcd 804'. Trees.

RWY 25: Thld dspcd 999'. Trees.

AIRPORT REMARKS: Unattended. Arpt clsd Nov-Apr and when snow covd. Birds, wildlife, snakes on & invof arpt. Rwy soft in spring & after rain. Remote island, no services, no shelter, no cell phone coverage. Overfly the fld before entering tfc pt. Watch for acft taxiing and taking off before ldg. Safety briefing and pilot info avbl at <https://theraf.org/>. Rwy not plowed. Tall trees alquads. Rwy 07-25 & dthr mkd with 3' yellow cones. See DNR rules posted near parking. Wind indicator unrel due to trees.

AIRPORT MANAGER: 248-761-5615

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Minneapolis ARTCC at 651-463-5588.

NORTHPORT

WOOLSEY MEML (5D5) 3 NE UTC-5(-4DT) N45°09.86' W85°34.53'

GREEN BAY

628 NOTAM FILE LAN

RWY 09-27: 3663X120 (TURF) LIRL

RWY 09: Thld dspcd 266'. Road.

RWY 27: Trees.

RWY 16-34: 2670X150 (TURF) 0.7% up N

RWY 16: Thld dspcd 770'. Trees.

RWY 34: Thld dspcd 300'. Trees.

SERVICE: LGT ACTIVATE LIRL Rwy 09-27—122.9.

AIRPORT REMARKS: Unattended. Arpt CLOSED Nov-Mar and when snow covered, except ski equipped acft. Birds and deer on and invof arpt. Rwy 09-27 slopes up E to W, and Rwy 16-34 slopes up N to S. Rwy 09-27 and Rwy 16-34 and dspcd thlds marked with 3' yellow cones.

AIRPORT MANAGER: 231-386-9841

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Minneapolis ARTCC at 651-463-5588.