

SIDNEY MUNI (N23) 1 W UTC-5(-4DT) N42°18.16' W75°24.96'


NEW YORK

1027 B NOTAM FILE BUF

L-30K, 32F, 33A

RWY 07-25: H4201X75 (ASPH) S-25, D-45 MIRL

IAP

RWY 07: REIL. Tree.**RWY 25:** REIL. PAPI(P2R)—GA 3.66° TCH 48'. Tree. Rgt tfc.**SERVICE:** S4 **FUEL** 100LL, JET A **OX** 3, 4 **LGT** ACTIVATE MIRL Rwy 07-25 and REIL Rws 07 and 25—CTAF.**AIRPORT REMARKS:** Attended 1300-2200Z. For attendant other times call 607-561-2346. Numerous hills surround arpt up to 800' abv arpt elevation. High tension lines 1 NM from AER 07. Two ft high cement fixtures in prim sfc in ditches 130 ft W of rwy. Fence 7 ft abv rwy end 325 ft of cntrln. Cold temperature airport. Altitude correction required at or below -21C.**AIRPORT MANAGER:** 607-561-2346**WEATHER DATA SOURCES:** AWOS-3 118.275 (607) 561-2333.**COMMUNICATIONS:** CTAF/UNICOM 122.8® **BOSTON APP/DEP CON** 133.25**CLEARANCE DELIVERY PHONE:** For CD ctc Boston ARTCC at 603-879-6859.**RADIO AIDS TO NAVIGATION:** NOTAM FILE BUF.**DELANCEY (L) (L) VORW/DME** 112.1 DNY Chan 58 N42°10.70' W74°57.42' 301° 21.8 NM to fld. 2560/11W.**ROCKDALE (L) (L) VORW/DME** 112.6 RKA Chan 73 N42°27.98' W75°14.35' 230° 12.6 NM to fld. 2032/11W.**SKANEATELES AERO DROME** (6B9) 2 SW UTC-5(-4DT) N42°54.84' W76°26.45'

NEW YORK

1039 TPA-1839(800) NOTAM FILE BUF

L-32F

RWY 04-22: 3350X130 (TURF) 0.8% up SW

IAP

RWY 04: Trees.**RWY 22:** Fence.**RWY 10-28:** H3134X58 (ASPH) S-9 MIRL(NSTD) 0.4% up W**RWY 10:** REIL. Thld dsplcd 243'. Trees.**RWY 28:** REIL. Trees.**SERVICE:** **FUEL** 100LL **LGT** Arpt lgt OTS indef. ACTIVATE MIRL Rwy 10-28—CTAF.**AIRPORT REMARKS:** Unattended, call manager. Fuel avbl 24 hr self svc credit card. Rwy 28 two 55' power poles 70' either side centerline 700' from thld. Rwy 04-22 avbl 15 May to 15 Oct. Rwy 10-28 NSTD MIRL. lghts are 38' from pavement edge. Rwy 28 has 4 lghts out and 2 lghts very dim. One thld lgt is rotated 90° (red/green lens). Rwy 10 3' fence 20' from thld on both sides, 15' road 30' from thld on both sides and 4' fence 80' from thld on both sides. -10' culvert/ditch 50' left of centerline at thld. Rwy 04-22 has variations in rwy sfc.**AIRPORT MANAGER:** 707-580-9240**WEATHER DATA SOURCES:** AWOS-3P 120.125 (315) 685-5790.**COMMUNICATIONS:** CTAF/UNICOM 122.8® **SYRACUSE APP/DEP CON** 126.125**CLEARANCE DELIVERY PHONE:** For CD ctc Syracuse Apch at 315-455-6218.**RADIO AIDS TO NAVIGATION:** NOTAM FILE SYR.**SYRACUSE (VH) (H) VORTACW** 117.0 SYR Chan 117 N43°09.63' W76°12.27' 226° 18.1 NM to fld. 453/11W.

TACAN AZIMUTH unusable:

Byd 35 NM blo 4,000'

VOR unusable:

010°-025°

026°-066° byd 40 NM

067°-077° byd 30 NM

078°-133° byd 40 NM

134°-144° byd 19 NM

145°-216°

217°-227° byd 40 NM blo 18,000'

228°-288° byd 40 NM

289°-299° byd 40 NM blo 2,300'

289°-299° byd 47 NM

300°-351° byd 40 NM

352°-009° byd 40 NM blo 3,000'

352°-009° byd 57 NM

DME unusable:

Byd 35 NM blo 4,000'

